

Inspection Photos

Location Name: GUNNISON ENERGY LLC, FEDERAL-610S90W/32SWSE

Location ID: 324459

Date: 8/17/2023



North Entrance to Location – Photo #05944



South End of Location – Photo #05945

Inspection Photos

Location Name: GUNNISON ENERGY LLC, FEDERAL-610S90W/32SWSE

Location ID: 324459

Date: 8/17/2023



SW Corner of Location – Photo #05946

Wellhead – Photo #05947

Inspection Photos

Location Name: GUNNISON ENERGY LLC, FEDERAL-610S90W/32SWSE

Location ID: 324459

Date: 8/17/2023



Separator – Photo #05949



Tank Battery – Photo #05950

Inspection Photos

Location Name: GUNNISON ENERGY LLC, FEDERAL-610S90W/32SWSE

Location ID: 324459

Date: 8/17/2023



**Water in Wellhead Cellar/Bradenhead Valve Not Accessible –
Photo #05948**



Insufficient BMPs at Ditch Crossing – Photo #05953

Inspection Photos

Location Name: GUNNISON ENERGY LLC, FEDERAL-610S90W/32SWSE

Location ID: 324459

Date: 8/17/2023



Insufficient BMPs at Ditch Crossing – Photo #05954



Unprotected Soil Stockpiles at Clear Fork Crossing – Photo #05917

Inspection Photos

Location Name: GUNNISON ENERGY LLC, FEDERAL-610S90W/32SWSE

Location ID: 324459

Date: 8/17/2023



Unprotected Soil Stockpiles at Clear Fork Crossing – Photo #05920



Unprotected Soil Stockpiles at Clear Fork Crossing – Photo #05921

Inspection Photos

Location Name: GUNNISON ENERGY LLC, FEDERAL-610S90W/32SWSE

Location ID: 324459

Date: 8/17/2023



**Lease Road Degradation at Clear Fork Crossing – Photo
#05923**