

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
403502191

Date Received:
08/18/2023

FIR RESOLUTION FORM

Overall Status:

CA Summary:

7 of 7 CAs from the FIR responded to on this Form

7 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10515

Name of Operator: GUNNISON ENERGY LLC

Address: 1801 BROADWAY #1150

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Johnston, Tyson dnr_cogccenforcement@state.co.us

Kosola, Jason tyson.johnston@oxbow.com

Grey, Daniel jason.kosola@state.co.us

geops@oxbow.com

daniel.gray@usda.gov

wtoews@blm.gov

COGCC INSPECTION SUMMARY:

FIR Document Number: 696205092

Inspection Date: 07/10/2023

FIR Submit Date: 07/12/2023

FIR Status: _____

Inspected Operator Information:

Company Name: GUNNISON ENERGY LLC

Company Number: 10515

Address: 1801 BROADWAY #1150

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 453805

Location Name: Trail Gulch Unit 1090 Number: 30 County: _____

Qtrqtr: SWSE Sec: 30 Twp: 10S Range: 90W Meridian: 6

Latitude: 39.157036 Longitude: -107.477597

FACILITY - API Number: 05-051- -00 Facility ID: 453805

Facility Name: Trail Gulch Unit 1090 Number: 30

Qtrqtr: SWSE Sec: 30 Twp: 10S Range: 90W Meridian: 6

Latitude: 39.157036 Longitude: -107.477597

CORRECTIVE ACTIONS:

1 CA# 175216

Corrective Action:

Date: 07/10/2023

Install or maintain BMP to ensure secondary containment remains impervious to contain a spill or release. The "Date of Discovery" is being provided as the corrective action date. Location will remains out of compliance until corrective actions have been resolved.

Response: CA COMPLETED

Date of Completion: 07/14/2023

Operator Comment: Burrow under tank battery checked for wildlife, filled and repaired. Inspection of liner showed no damage. See photo.

COGCC Decision: _____

COGCC Representative: _____

2 CA# 175217

Corrective Action: Comply with 606 Rules. The "Date of Discovery" is being provided as the corrective action date. Location will remains out of compliance until corrective actions have been resolved.

Date: 07/11/2023

Response: CA COMPLETED

Date of Completion: 07/14/2023

Operator Comment: Equipment, hoses and unused materials removed from tank area. Barrel remains in separate containment inside of tank containment to protect from wind. See photos.

COGCC Decision: _____

COGCC Representative: _____

3 CA# 175218

Corrective Action: Comply with Rule 605.h. The "Date of Discovery" is being provided as the corrective action date. Location will remains out of compliance until corrective actions have been resolved.

Date: 07/10/2023

Response: CA COMPLETED

Date of Completion: 07/14/2023

Operator Comment: Tank Battery signage shown in the attached photos were omitted from inspection photos. This sign, inside of containment and outside of containment on both ends containing all operator, emergency, location and other information has been there. See photos. "Oil Tank" also blacked out from Tank 3.

COGCC Decision: _____

COGCC Representative: _____

4 CA# 175219

Corrective Action: Properly secure/close hatch at tank. The "Date of Discovery" is being provided as the corrective action date. Location will remains out of compliance until corrective actions have been resolved.

Date: 07/10/2023

Response: CA COMPLETED

Date of Completion: 07/14/2023

Operator Comment: Hatch on sand can properly secured. See photo.

COGCC Decision: _____

COGCC Representative: _____

5 CA# 175220

Corrective Action:

Date: 07/10/2023

Comply with Rule 1002.f and install or repair BMPs to minimize erosion/degradation/sediment transport, and to protect/stabilize the cut slopes of the Location. The "Date of Discovery" is being provided as the corrective action date. Location will remain out of compliance until corrective action has been resolved.

Response: CA COMPLETED

Date of Completion: 07/14/2023

Operator Comment: Substantial Growth shown with wet spring/summer. Torrential rains seen in the spring did cause some minor erosion in spots, however, secondary measures including ditches, and catch basin, were able to keep 100% of all stormwater on location. Minor erosion areas were repaired and areas where hydroseed did not work will be seeded again in the fall when growth is most likely. Straw will be used in the interim to prevent further erosion. See slope growth photos 1-3.

COGCC Decision: _____

COGCC Representative: _____

6 CA# 175221

Corrective Action: Comply with Rule 1003.a. The "Date of Discovery" is being provided as the corrective action date. Location will remain out of compliance until corrective action is resolved.

Date: 07/10/2023

Response: CA COMPLETED

Date of Completion: 07/14/2023

Operator Comment: Anchor marker replaced.

COGCC Decision: _____

COGCC Representative: _____

7 CA# 175222

Corrective Action: Comply with 1002.f; implement BMPs at the excavated areas of the ditch along east end of the Location, in order to prevent potential impacts to stormwater runoff/runoff.

Date: 11/01/2022

Response: CA COMPLETED

Date of Completion: 07/14/2023

Operator Comment: Photo 14 was the remanence of impacted soils that were removed in accordance with Form 27 Doc. No. 403225349. Remnant holes have been back filled.

COGCC Decision: _____

COGCC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: _____

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Tyson Johnston

Signed: _____

Title: Vice President

Date: 8/18/2023 3:47:50 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403502206	Filled Burrow
403502216	Containment equipment cleanup 1
403502219	Containment equipment cleanup 2
403502220	Containment equipment cleanup 3
403502236	Tank Battery Sign inside containment
403502237	Tank Battery Sign outside containment
403502241	Sand Can Hatch
403502257	Slope Growth
403502265	Slope Growth 3
403502268	Slope Growth 2

Total Attach: 10 Files