

RECEIVED

MAY - 6 1968



00640096

AND GAS CONSERVATION COMMISSION OF THE STATE OF COLORADO

File in duplicate for Patented and Federal lands.
File in triplicate for State lands.

COLO. OIL & GAS CONS. COMM.

LEASE DESIGNATION AND SERIAL NO.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER Dry Hole		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
2. NAME OF OPERATOR Horizon Oil & Gas Co.		7. UNIT AGREEMENT NAME Horizon Oil & Gas Co.	
3. ADDRESS OF OPERATOR P.O. Box #7, Spearman, Texas 79081		8. FARM OR LEASE NAME Bruchie	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface Same At proposed prod. zone Same		9. WELL NO. 1-25	
14. PERMIT NO. X NONE		10. FIELD AND POOL, OR WILDCAT Flank - Topeka "A"	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3875 G.L.		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 25, Twp. 33S, Rge. 43W	
		12. COUNTY OR PARISH Baca	13. STATE Colorado

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT

(Other)

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Plugging Date: May 6, 1968

Time: 10:00 a.m. (est.)

Plugging Procedure:

Set a plug @ 2600' with 1 sack cement on top. (Plug @ 2600' is Cast Iron Bridge Plug)

Set 25 sack plug @ 313' (base of surface)

15' ~~25~~ sack plug at surface.

Weld on cap.

DVR	
FJP	✓
HHM	✓
JAM	✓
JJD	✓

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Production Manager

DATE May 3, 1968

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE MAY 7 1968

CONDITIONS OF APPROVAL, IF ANY.