

Inspection Photos

9/6/2023

Operator: TEP ROCKY MOUNTAIN LLC #96850

Location Number: 311852

Rio Blanco County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location Number: 311852



Photo 1: Photos 1-2 taken from the west end of the Location. Photos provide an overview of the Location from north, northeast, southeast to south.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC #96850
Location Number: 311852



Photo 2: See comments under photo 1.



Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC #96850
Location Number: 311852



Photo 3: Photo shows riser equipment associated with abandoned wells remain on the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC #96850
Location Number: 311852





Photo 4: Photos taken from the methanol tank on the east end of the Location. A crack in the tank has resulted in fluids spilling onto the working pad surface



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC #96850
Location Number: 311852



Photo 5: Continued from photo 4. Arrow shows crack within tank resulting in spill.



Inspection Photo
Operator Name: TEP ROCKY MOUNTAIN
Location Number: 3



Photo 6: Photos taken from the northeastern cut slopes of the Location. Slopes lack stabilization.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location Number: 311852



Photo 7: Photos taken from the slopes on the eastern interim areas of the Location. Operator has implemented hydromulch in conjunction with surface roughening. Hydromulch show signs of disrepair.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC #96850
Location Number: 311852



Photo 8: Unused batteries improperly stored on Location. Methanol tank also appears to be unused.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location Number: 311852



Photo 9: Unused pipe stored within the containment BMP of the battery facility.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location Number: 311852



Photo 10: Photos taken from the east end of the tank battery facility. Photo shows stained soils.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC #96850
Location Number: 311852



Photo 11: Subsidence concerns observed on the west end of the battery facility.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location Number: 311852



Photo 12: Photos examples of the interim areas of the Location. Interim reclamation “in process”.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location Number: 311852



Photo 13: Photo example of Halogeton observed on the interim areas. Weeds were observed in low densities, though spread throughout the entire interim areas.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources