

# Inspection Photos

9/6/2023

Operator: TEP ROCKY MOUNTAIN LLC #96850

Location Number: 439690

Rio Blanco County, CO

Aaron Trujillo  
NW Reclamation Specialist  
CECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location Number: 439690



**Photo 1:** Photos 1-2 taken from the west end of the Location. Photos provide an overview of the Location from north, northeast, southeast to south.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC #96850  
Location Number: 439690



**Photo 2:** See comments under photo 1.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location Number: 439690



**Photo 3:** Photo example of erosion degradation at the northern location entrance; erosion apparent on both the east and west sides of the location entrance road.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location Number: 439690



**Photo 4:** Photo example of areas within the stormwater diversion ditch that has largely filled with sediment.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location Number: 439690



September 6, 2023



September 6, 2023

**Photo 5:** Photos taken from the topsoil stockpile on the southeast end of the Location. Vegetation is predominantly Undesirable Weedy Plant Species such as cheatgrass and tumble mustard. Desirable plant establishment only observed at the toe of the soil stockpile.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location Number: 439690



**Photo 6:** Photo taken from the west end of the Location. Pit has not been constructed. Surface roughening remains in proper functioning condition within these areas.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location Number: 439690



September 6, 2023



September 6, 2023

**Photo 7:** Photos taken from the east western areas of the Location. Stormwater and erosion control measures within these areas are not longer in proper functioning condition. Erosion and sediment transport/deposition observed.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location Number: 439690



**Photo 10:** Photos show unstabilize soils remain on the working pad surface.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location Number: 439690



**Photo 10:** Photos show unstabilize soils remain on the working pad surface.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location Number: 439690



**Photo 11:** Cut slopes lack stabilization and BMPs to minimize erosion and degradation. Arrow shows sediment deposition due to erosion at the cut slopes.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location Number: 439690



**Photo 11:** Cut slopes lack stabilization and BMPs to minimize erosion and degradation.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection  
Operator Name: TEP ROCKY  
Location Num



September 6, 2023



September 6, 2023

**Photo 12:** Cut slopes lack stabilization and BMPs to minimize erosion and degradation.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC #96850  
Location Number: 439690



**Photo 13:** Signage missing at well.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC #96850  
Location Number: 439690



September 6, 2023

**Photo 14:** Unused culvert/pipe.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources