

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/31/2023

Submitted Date:

09/08/2023

Document Number:

709100099

**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: Heibel, Krystal On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 81720  
 Name of Operator: STANDLEY\* ROBERT K DBA OTIS ENERGY  
 Address: 315 SOUTH VINE STREET  
 City: OTIS State: CO Zip: 80743

**Findings:**

- 10 Number of Comments
- 9 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Ellen Standley		venture2.es@gmail.com	
Krystal Heibel	303-817-5217	krystal.heibel@state.co.us	
Robert Standley	970-246-3439	standleyent@msn.com	

**General Comment:**

This is an environmental progress inspection. Any corrective actions from previous inspections that have not been addressed are still applicable. Photos attached to document site conditions.

On Thursday 08/31/2023, an environmental inspection was performed for the GEOGLEIN 5 pits location. Operator personnel was not present during time of inspection. Photos attached to document site conditions.

Operator Name: STANDLEY\* ROBERT K DBA OTIS ENERGY  
 Location Name: GEOGLEIN-62N49W 13SWSE #1  
 Pit #1, Location ID: 112603  
 Pit #2, Location ID: 103432  
 Pit #3, Location ID: 103433  
 County: Washington County, Colorado

This inspection is a follow-up, in response to the previous Inspection Report (Doc #709100010) conducted on 3/23/2023.

Location						
Overall Good: <input type="checkbox"/>						
<b>Signs/Marker:</b>						
Type	BATTERY					
Comment:	Emergency contact # illegible from a distance.					
Corrective Action:	Comply with Rule 605.e.				Date:	05/05/2023
Emergency Contact Number:						
Comment:	Emergency contact # illegible from a distance.					
Corrective Action:	Comply with Rule 605.e. and g.				Date:	05/05/2023
<b>Good Housekeeping:</b>						
Type	WEEDS					
Comment:	Undesirable vegetation on Site, including on pit berms and around unused equipment.					
Corrective Action:	Comply with Rule 1003.f.				Date:	10/09/2023
Type	UNUSED EQUIPMENT					
Comment:	Unused equipment left onsite (two barrels of oil, sheets of wood, metal piping).					
Corrective Action:	Comply with 902.b. Any unused equipment needs to be removed and the crude oil in the barrels need to be properly disposed of as E&P waste.				Date:	05/05/2023
Overall Good: <input type="checkbox"/>						
<b>Spills:</b>						
Type	Area	Volume				
Crude Oil	Tank	<= 1 bbl				
Comment:	Hydrocarbons observed leaking from top of tank. Observed to be an inactive leak.					
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a.				Date:	10/09/2023
Crude Oil	Tank	<= 1 bbl				
Comment:	Hydrocarbon stained soils observed around a buried vessel. (See photo documentation)					
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a. and identify the buried vessel and it's contents to ECMC staff (Environmental Protect Specialist Krystal Heibel via 303-817-5217) .				Date:	10/09/2023
In Containment: No						
Comment:						
<input type="checkbox"/> Multiple Spills and Releases?						
<b>Equipment:</b>						
Type: Other	#				corrective date	
Comment:	Tank battery valves are not sealed.					
Corrective Action:	Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.				Date:	09/23/2023
<b>Tanks and Berms:</b>						
Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	2	<50 BBLs	STEEL AST		,	
Comment:	Wildlife protections devices not adequate for the Entry Hatch/Inspection Hatch for both tanks. Unauthorized discharge or disposal of oil, gas, E&P Waste, chemical substances, trash discarded equipment or other oil field waste.					

Corrective Action:	Install or repair wildlife protection equipment. Prevent any unauthorized discharge.	Date:	09/18/2023
--------------------	--	-------	------------

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Insufficient	Base Insufficient	Inadequate
Comment:	Berms around each pit are eroding. Burrows were observed, and undesirable vegetation observed within pit and on the berms. Berms non-existent around tank battery and unused tank located on site.			
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 603.o.			Date:
				10/09/2023

**Venting:**

Yes/No			
Comment:			
Corrective Action:			Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
709100100	Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6245473">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6245473</a>