




99999999

103-06374

(SUBMIT IN TRIPLICATE)

Budget Bureau No. 42-R358.4.
Approval expires 12-31-60.Land Office DenverLease No. 0338045

Unit _____

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

November 21, 1957

Well No. 1 is located 1110 ft. from N line and 396 ft. from E line of sec. 11

NE SE SE SEC. 11 1N 102W 6th P.M.
 (¼ Sec. and Sec. No.) (Twp.) (Range) (Meridian)

Rangely Rio Blanco Colorado
 (Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Bridged the hole at 30 feet and filled the top 25 feet of the hole with cement, with a 6 foot marker. There was only one formation drilled, so plugs for different formations should not be necessary. No gas was encountered.

Approved 2-16-60*Asst. District Engineer*

00044039

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Jack White Drilling CompanyAddress Phoenix, ArizonaBy O.M. Hegwer
O.M. Hegwer

Title _____