

WELL NAME: KELSALL 33-7 #4-1, 4-2, 4-3 & 4-4, API #: 067-09866, INSP. # 695108632



PHOTO 1: WELL SIGN/ METER AND FIRED SEPARATOR HOUSE.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



PHOTO 2: WELL SIGN/ METER AND FIRED SEPARATOR HOUSE.





PHOTO 3: LOCATION





PHOTO 4: WELLHEAD AND EQUIPMENT. NO WELL SIGN IDENTIFYING EACH WELL. POST SIGN PER RULE 605 10-6-2023.





PHOTO 5: WELLHEAD AND EQUIPMENT. NO WELL SIGN IDENTIFYING EACH WELL. POST SIGN PER RULE 605 10-6-2023.





PHOTO 6: WEED MAINTENANCE AROUND PUMP JACKS. MAINTIAN WEEDS PER RULE 606. CA DATE 10-6-2023.





PHOTO 7: WEED MAINTENANCE AROUND PUMP JACKS. MAINTIAN WEEDS PER RULE 606. CA DATE 10-6-2023.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources




PHOTO 8: WEED MAINTENANCE AROUND PUMP JACKS. MAINTIAN WEEDS PER RULE 606. CA DATE 10-6-2023.





PHOTO 9: Produced water spill from the wellhead has left a salt/mineral impacted area around the wellhead. Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition and dispose of impacted materials per Rule 608.e. ca date 10-6-2023.





PHOTO 10: Oily waste appears to be from rod box impacting soil near wellhead. Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition and dispose of impacted materials per Rule 608.e. ca date 10-6-2023.





PHOTO 11: Oily waste appears to be from pump jack prime mover is impacting soil near prime mover. Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition and dispose of impacted materials per Rule 608.e. ca date 10-6-2023.





PHOTO 12: Tall weeds on and inside berms. Maintain berms/ remove weeds along with there root structures per rule 605.a. ca date 10-6-2023.





PHOTO 13: Tall weeds on and inside berms. Maintain berms/ remove weeds along with there root structures per rule 605.a. ca date 10-6-2023.





PHOTO 14: There are several anchor markers down or missing throughout location. **Install proper guy line markers per Rule 1003.a ca date 10-6-2023.**





PHOTO 15: There are several anchor markers down or missing throughout location. **Install proper guy line markers per Rule 1003.a ca date 10-6-2023.**



**PHOTO 16: Noxious weeds ca from previous inspection appear to have been poisoned however they have been left on and around location .
Properly bag and dispose of noxious weeds per rule 1003.**





PHOTO 17: tank battery

