

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/14/2023

Submitted Date:

09/19/2023

Document Number:

710500010

FIELD INSPECTION FORM

Loc ID: 484359 Inspector Name: Sanchez, Chris On-Site Inspection: 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10797
Name of Operator: DESERT EAGLE OPERATING LLC
Address: 17101 PRESTON RD SUITE 105
City: DALLAS State: TX Zip: 75248

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 10 Number of Comments
- 5 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Beardslee, Tom		tom.beardslee@state.co.us	
Bulf, Cathy		cathybulf@gmail.com	Desert Eagle Operating llc
Butler, Brad	972-345-9195	butleroil@yahoo.com	Desert Eagle Operating llc
Sanchez, Chris		chris.sanchez@state.co.us	
Costa, Ryan		ryan.costa@state.co.us	

General Comment:

This is an Environmental Inspection for the Red Rocks 35-08, API # 05-071-09930; Location # 484676, active drilling location located in Las Animas County, Co
CA's From Reclamation inspection # 713600094 still apply.
Comply with Reclamation Inspection CA's and Dates.

Location

Lease Road:			
Type	Access		
comment:	Vehicle rutting observed at the time of inspection		
Corrective Action:	Maintain vehicle tracking BMP's on the oil and gas location to comply with rule 1002.f. (2)F. Comply with rule 1002 f	Date:	09/25/2023

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Unused Equipment observed on location		
Corrective Action:	Comply with rule 606	Date:	10/16/2023
Type	TRASH		
Comment:	Trash and Debris observed on location		
Corrective Action:	Comply with Rule 606.	Date:	09/25/2023

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No _____

Comment:

Multiple Spills and Releases?

Venting:			
Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Location Construction

Location ID: 484359 CDP: _____

Comment: Drill cuttings were not properly stored with a berm and liner as described in the waste management plan

Corrective Action: CA will maintain the original CA date of 8/15/2023 as outlined in Reclamation Inspection #713600094 on 8/15/2023

Date: 08/15/2023

Form 2A COAs:

Comment: _____

Corrective Action: _____

Date: _____

Wildlife BMPs:

Comment: _____

Corrective Action: _____

Date: _____

Comment: _____

Corrective Action: _____

Date: _____

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Environmental

Waste Management:

Type	Management	Condition	GPS (Lat)	(Long)
Drill Cuttings	Piles	Inadequate		
Comment	Drill cuttings were not stored with berm and liner as described in the waste management plan. The cuttings pile still remains with no berm, liner, or other BMP. Previous corrective action was not completed. Drill cutting storage, handling, transport, and disposal must comply with Rule 905. Please also refer to 905.b. E&P waste transportation for any offsite transportation of drill cuttings.			
Corrective Action	Comply with Rule 905. for Management of E&P Waste			Date: 08/15/2023

Spill/Remediation:

Comment:

Corrective Action: Date:

Emission Control Burner (ECB):

Comment:

Pilot: Wildlife Protection Devices (fired vessels):

COGCC Comments

Comment	User	Date
Subsidence noticed over top of pipe in Pipeline R-O-W; Operator shall adhere to Rule 1102.f.(2)	sanchezcc	09/15/2023
Comply with Rule 905. For Management of E&P waste	sanchezcc	09/15/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
710500012	710500010 Location Photos Red Rocks 35-08	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6255056