

Inspection Photos

9/19/2023

Operator: LARAMIE ENERGY LLC #10433

Location ID: 452807

Inspection No: 696205261

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 452807



Photo 1: Photos taken from the south end of the Working Pad Surface. Photos 1-2 provide an overview of the Location from west, northwest, northeast to east. Photos also show frac operations have completed, and the majority of the tanks and other related equipment have been removed. Interim reclamation now required.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 452807



Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 452807



Photo 2: Photo taken from the south end of the Location. Photo shows stained soils observed next to the pipeline equipment.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location ID: 452807



Photo 4: Photo taken from the south end of the Location. Photo shows porta-john has been secured, and spill has been cleaned.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location ID: 452807



September 19, 2023



September 19, 2023

Photo 5: Photo shows single tank remaining on the Location from frac Operations. Photo also show tank labeling remains out of compliance with 605 rules.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 452807



Photo 6: Photos taken from the Location entrance, on the southwest end of the Location. Photos show control measures to stabilize slopes remain missing or insufficient.

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 452807



Photo 7: Photos examples showing an unknown black material that has been spilled upon the working pad surface, and areas of the access road.