

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403544183

Date Received:

09/28/2023

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10133
Name of Operator: HILCORP ENERGY COMPANY
Address: P O BOX 61229
City: HOUSTON State: TX Zip: 77208

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name Phone
Labowskie, Steve
.General

Email
steve.labowskie@state.co.us
FarmingtonRegulatoryTechs@hilcorp.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 712700659

Inspection Date: 09/14/2023

FIR Submit Date: 09/15/2023

FIR Status: _____

Inspected Operator Information:

Company Name: HILCORP ENERGY COMPANY

Company Number: 10133

Address: P O BOX 61229

City: HOUSTON State: TX Zip: 77208

LOCATION - Location ID: 325510

Location Name: DAVIS GAS UNIT-N33N10W Number: 4NENW County: LA PLATA

Qtrqtr: NENW Sec: 4 Twp: 33N Range: 10W Meridian: N

Latitude: 37.137310 Longitude: -107.942500

FACILITY - API Number: 05-067- -00 Facility ID: 214920

Facility Name: DAVIS GAS UNIT Number: 1

Qtrqtr: NENW Sec: 4 Twp: 33N Range: 10W Meridian: N

Latitude: 37.137310 Longitude: -107.942500

CORRECTIVE ACTIONS:

1 CA# 181213

Corrective Action: Mark per Rule 1003.a. or remove not serviceable or no longer needed for ongoing operations.

Date: 09/29/2023

Response: CA COMPLETED

Date of Completion: 09/27/2023

Operator Comment: Marked all rig anchors on location. See attached photos.

COGCC Decision:

Date Run: 9/28/2023 Doc [#403544183]

COGCC
Representative:

2 CA# 181214

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C.

Date: 09/29/2023

Response: CA COMPLETED

Date of Completion: 09/27/2023

Operator Comment: Installed and repaired BMPs on eastern side of location and mitigated sediment migration off location. Repaired and reinforced overwhelmed ditch and Berm along west side of location. See attached photos

COGCC Decision:

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Priscilla Shorty

Signed:

Title: OperationsRegulatory Tech

Date: 9/28/2023 10:10:57 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

403544185	Davis Gas Unit 1_712700659_Resolved Photos
-----------	--

Total Attach: 1 Files