



Marked all rig anchors on location







Installed and repaired BPMs on eastern side of location and mitigated sediment migration off location









Repaired and reinforced overwhelmed ditch and Berm along west side of location

