

State of Colorado  
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:  
403520431

Date Received:  
09/05/2023

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 69175

Name of Operator: PDC ENERGY INC

Address: 1099 18TH STREET SUITE 1500

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Tyranny Bergin

970-313-5547

EHSCOGCCInspections@pdce.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 701900648

Inspection Date: 09/03/2022

FIR Submit Date: 12/27/2022

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: PDC ENERGY INC

Company Number: 69175

Address: 1775 SHERMAN STREET - STE 3000

City: DENVER State: CO Zip: 80203

LOCATION - Location ID: 327499

Location Name: KEISER-64N66W Number: 28SENW County: \_\_\_\_\_

Qtrqr: SENW Sec: 28 Twp: 4N Range: 66W Meridian: 6

Latitude: 40.283496 Longitude: -104.785011

FACILITY - API Number: 05-123-00 Facility ID: 327499

Facility Name: KEISER-64N66W Number: 28SENW

Qtrqr: SENW Sec: 28 Twp: 4N Range: 66W Meridian: 6

Latitude: 40.283496 Longitude: -104.785011

CORRECTIVE ACTIONS:

1  CA# 166764

Corrective Action: Comply with Rule 1004. Reseed disturbance areas using a seed mixture requested by the surface owner, or a mixture prescribed by the local county NRCS. Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of reference area levels. Ensure erosion controls are implemented to stabilize the seeded soil. Operator shall continue to monitor and manage this site until the location meets Rule 1004 standards, including stormwater and weed management.

Date: 09/03/2022

The corrective date is not intended to be the date for which the Operator shall complete the corrective actions but rather the corrective date is the date the location was observed out of compliance.

Response: CA COMPLETED

Date of Completion: 08/15/2023

Operator Comment: Work has been completed and will continue to monitor. Landowner has stated that the access point and culvert, referenced in the CA are historical and have been used to access the field all along the East side. Attached is a google map from 1999 for reference showing the scaring along the field break, east and west, along the entire property. CA complete.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC standards.

**OPERATOR COMMENT AND SUBMITTAL**

Comment: Work has been completed and will continue to monitor. Landowner has stated that the access point and culvert, referenced in the CA are historical and have been used to access the field all along the East side. Attached is a google map from 1999 for reference showing the scaring along the field break, east and west, along the entire property. CA complete.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Tyranny Bergin Signed: \_\_\_\_\_

Title: Safety Representative Date: 9/5/2023 3:26:07 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<b>Document Number</b>	<b>Description</b>
403520431	FIR RESOLUTION SUBMITTED
403520441	Historical Map
403520448	Inspection Photos
403520449	Work Done 1
403520451	Work Done 2

Total Attach: 5 Files