

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/10/2023

Submitted Date:

10/10/2023

Document Number:

707901150

FIELD INSPECTION FORMLoc ID 322273 Inspector Name: Silver, Randy On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 44390

Name of Operator: JAVERNICK OIL

Address: 3040 E MAIN

City: CANON CITY State: CO Zip: 81212

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

10 Number of Comments

5 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Javernick, James	719-275-3040/719-671-3787	javernick1@gmail.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210096	WELL	PR	04/01/2023	OW	043-40033	CONOCO FEE 66 492	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Placard and peeling off		
Corrective Action:	Install sign to comply with Rule 605		Date: 01/19/2023
Type	WELLHEAD		
Comment:	Sign not posted or information inaccurate at oil and gas location		
Corrective Action:	Install sign to comply with Rule 605.a.		Date: 11/10/2023

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Stained soil under load out line container		
Corrective Action:	For localized stained soils or oily waste - ""Properly dispose of oily waste in accordance with 905.e.""		Date: 01/19/2023
Type	UNUSED EQUIPMENT		
Comment:	Plastic tote, stairs in disrepair		
Corrective Action:	Comply with rule 606		Date: 01/19/2023
Type	TRASH		
Comment:	rocks wood and debris in and around crude oil tank containment		
Corrective Action:	Comply with rule 606		Date: 01/19/2023

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment:	Gasoline powered motor		
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:			

Corrective Action:		Date:	
--------------------	--	-------	--

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	1	OTHER	STEEL AST		,	

Comment:						
Corrective Action:					Date:	

Paint

Condition					
Other (Content)					
Other (Capacity)	210BBL				
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment:						
Corrective Action:					Date:	

Venting:

Yes/No					
Comment:					
Corrective Action:				Date:	

Flaring:

Type					
Comment:					
Corrective Action:				Date:	

Inspected Facilities

Facility ID: 210096 Type: WELL API Number: 043-40033 Status: PR Insp. Status: PR

Producing WellComment: PR

Corrective Action:

Date:

BradenHeadDate of Last Brhd Test: 02/22/2022Annual Brhd Completed? NoLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONEEnd Surf Csg Pressure: 0Comment: Submit reports

Corrective Action:

Date:

COGCC Comments

Comment

User

Date

COGCC Inspection Report Summary On Tuesday October 10, 2023 at approximately 12:45PM, I, Inspector Randy Silver, conducted an on-site re-inspection Per doc#707900367. Location: Conoco Fee 66#492 Operator: Javernick Oil API#:043-40033 County: Freemont While there, I observed a producing well and Tank Battery During this inspection the following possible compliance issues were observed: Trash/debris: Rule 606 Corrective action date of 1-19-22 , NFPA placard: Rule 605 Corrective action date of 1-19-22 , Stained soil: Rule 905 e Corrective action date of 1-19-22, Unused equipment: Rule 606 Corrective action date of 1-19-22 , Sign: Rule 605A Corrective action date of 11-10-23 Weather conditions: Clear. At time of inspection it did not appear any corrective actions have been addressed. A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report

silverr

10/10/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707901151	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6279968