

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:

403557324

Date Received:

10/11/2023

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10758

Name of Operator: OGRIS OPERATING LLC

Address: PO BOX 53467

City: MIDLAND State: TX Zip: 79710

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Ogris

719-220-4041

gward@ogrisop.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 713600233

Inspection Date: 09/18/2023

FIR Submit Date: 09/19/2023

FIR Status: _____

Inspected Operator Information:

Company Name: OGRIS OPERATING LLC

Company Number: 10758

Address: PO BOX 53467

City: MIDLAND State: TX Zip: 79710

LOCATION - Location ID: 308913

Location Name: GOLDEN EAGLE-633S67W Number: 18SWSE County: LAS ANIMAS

Qtrqtr: SWSE Sec: 18 Twp: 33S Range: 67W Meridian: 6

Latitude: 37.166170 Longitude: -104.926050

FACILITY - API Number: 05-071-

-00

Facility ID: 284808

Facility Name: GOLDEN EAGLE

Number: 18-15

Qtrqtr: SWSE Sec: 18 Twp: 33S Range: 67W Meridian: 6

Latitude: 37.166170 Longitude: -104.926050

CORRECTIVE ACTIONS:

1 CA# 181481

Corrective Action: Comply with 1003.f. and 606.

Date: 09/18/2023

Response: CA COMPLETED

Date of Completion: 09/26/2023

Operator
Comment:

THE NOXIOUS WEEDS ON THE FILL SLOPE WERE TREATED ON 9/26/23. THE LOCATION WILL BE RE-TREATED AS NEEDED.

COGCC Decision:

COGCC
Representative:

2 CA# 181482

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)

Date: 09/18/2023

Response: CA COMPLETED

Date of Completion: 10/11/2023

Operator
Comment:

A DIVERSION DITCH WAS CREATED ALONG THE TOP OF THE FILL SLOPE TO DIRECT STORM WATER OFF LOCATION AND PREVENT RILLING ON THE SLOPE. ROCK CHECK DAMS WERE INSTALLED TO CONTROL RUN ON VELOCITY. STRAW BLANKETS WERE INSTALLED OVER THE ENTIRE FILL SLOPE. ALL DISTIRBED AREAS WERE TRACKED, SEEDED, AND HYDROMULCHED TO FURTHER PROMOTE STABILIZATION THROUGH VEGETATIVE GROWTH.

COGCC Decision:

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: ALL CORRECTIVE ACTIONS HAVE BEEN COMPLETED. SEE PHOTO LOG FOR DETAILS.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: GIENA ZECHES

Signed:

Title: ENVIRONMENTAL

Date: 10/11/2023 1:25:39 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

403557355	PHOTO LOG
-----------	-----------

Total Attach: 1 Files