

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/26/2023

Submitted Date:

10/05/2023

Document Number:

694100183

FIELD INSPECTION FORMLoc ID 332984 Inspector Name: Robinson, Taylor On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 69175

Name of Operator: PDC ENERGY INC

Address: 1099 18TH STREET SUITE 1500

City: DENVER State: CO Zip: 80202

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

8 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogccinspection@pdce.com	All Inspections
,		COGCCInspection@pdce.com	All Inspections
,		cogccinspection@pdce.com	All Inspections

General Comment:

This is an environmental inspection for Location ID 332984 Village/Leonard and Sons pad. Any corrective actions from previous inspections that have not been addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: 10/19/2023**Good Housekeeping:**

Type

Comment: Corrective Action: Date: 10/19/2023Overall Good: ☐**Spills:**

Type

Area

Volume

In Containment: NoComment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Location Construction

Location ID: 332984 CDP: _____

Comment: _____

Corrective Action: _____

Date: _____

Form 2A COAs:

Comment: _____

Corrective Action: _____

Date: _____

Wildlife BMPs:

Comment: _____

Corrective Action: _____

Date: _____

Comment: Large rills on site, sediment washout throughout site, discharge of sediment leaving pad.
Needs to be regraded and sediment pulled back.

Corrective Action: Stormwater management Erosion Control. Install or repair required BMPs per Rule 1002.f.(2)C

Date: 10/12/2023

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____

Phone Number: _____

Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Environmental**Spills/Releases:**

Type of Spill:	_____	Estimated Spill Volume:	_____		
Comment:	<div>No indication of spills on pad location during inspection.</div>				
Corrective Action:	<div></div>		Date:	_____	
Reportable:	_____	GPS: Lat	_____	Long	_____
Proximity to Surface Water:	_____	Depth to Ground Water:	_____		

Water Well Complaint:

			Lat	Long	
DWR Receipt Num:	_____	Owner Name:	_____	GPS :	_____

Field Parameters:

<div></div>			
Sample Location:	_____	Comment:	_____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403552143	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6275731
694100184	photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6275720