

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403569481

Date Received:

10/23/2023

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10665

Name of Operator: CCRP OPERATING INC

Address: 12136 W BAYAUD AVE STE 320

City: LAKEWOOD State: CO Zip: 80228

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Jon Anderson

970-373-7397

janderson@rockiesresourcesllc.com

Cody Duran

303-880-0790

cduran@rockiesresourcesllc.com

logan.hansen@state.co.us

COGCC INSPECTION SUMMARY:

FIR Document Number: 697504897

Inspection Date: 10/11/2023

FIR Submit Date: 10/17/2023

FIR Status: _____

Inspected Operator Information:

Company Name: CCRP OPERATING INC

Company Number: 10665

Address: 12136 W BAYAUD AVE STE 320

City: LAKEWOOD State: CO Zip: 80228

LOCATION - Location ID: 418853

Location Name: Lion Creek Number: 4-16H County: _____

Qtrqtr: SESE Sec: 16 Twp: 11N Range: 64W Meridian: 6

Latitude: 40.914992 Longitude: -104.543400

FACILITY - API Number: 05-123- -00 Facility ID: 418853

Facility Name: Lion Creek Number: 4-16H

Qtrqtr: SESE Sec: 16 Twp: 11N Range: 64W Meridian: 6

Latitude: 40.914992 Longitude: -104.543400

CORRECTIVE ACTIONS:

1 ☒ CA# 185304

Corrective Action: Repair or install berms or other secondary containment devices per Rule 603.o.

Date: 10/11/2023

The corrective action date is the date the location was observed out of compliance.

Response: CA COMPLETED

Date of Completion: 10/19/2023

Berms were raised to meet 603.o on 10/19. Photos attached.

Operator
Comment:

COGCC Decision: Approved via an AMI

COGCC Representative: Approved via an AMI of this FIR resolution acknowledges the document and attachments were received. Based on the attached photos, Operator has completed the corrective action. A field inspection will be conducted at a future date to evaluate compliance with COGCC standards.

2 ☒ CA# 185305

Corrective Action: Install sign to comply with Rule 605.e.

Date: 10/11/2023

The corrective action date is the date the location was observed out of compliance.

Response: CA COMPLETED

Date of Completion: 10/19/2023

Operator
Comment:

Signage was updated with current operator CCRP 10/19

COGCC Decision: Approved via an AMI

COGCC Representative: Approved via an AMI of this FIR resolution acknowledges the document and attachments were received. Based on the attached photos, Operator has completed the corrective action. A field inspection will be conducted at a future date to evaluate compliance with COGCC standards.

OPERATOR COMMENT AND SUBMITTAL

Comment: Berms were raised and signage on 10/19. Corrective Actions have been completed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Cody Duran

Signed: _____

Title: Production Engineer

Date: 10/23/2023 2:57:40 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403569481	FIR RESOLUTION SUBMITTED
403569614	Lion Creek 4-16H berm 1 after photo
403569620	Lion Creek 4-16H berm 2 after photo

Total Attach: 3 Files