

Interim Reclamation and Stormwater Inspection

Date: 10/17/2023

Operator: Verdad Resources LLC - 10651

Location ID: 472202

Inspection Document #: 713900027

Weld County, CO

Logan Hansen
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Timbro Fed 1931
Location ID: 472202



Photo 1. The photo was taken of the location sign. Photo illustrates produced water spilled into secondary containment as well as hoses outside secondary containment.



Colorado Energy & Carbon Management Commission
Weld County
+40.7301,-103.9067
134° SE
10/17/23, 2:35 PM

Photo 2. The photo was taken at the East end of the tank batteries facing Southeast. The photo illustrates produced water actively spilling into secondary containment.



Photo 3. The photo was taken at the well location entrance facing Northeast. The photo illustrates a gravel stockpile being stored on site. The stockpile is accumulating kochia and russian thistle.



Photo 4. The photo was taken at the east end of the well location facing Northwest. The photo illustrates a stormwater bmp with russian thistle and kochia growing throughout.



Photo 5. The photo was taken at the North end of the well location facing Northwest. The photo illustrates the seeded and mowed interim reclamation area.



Photo 6. The photo was taken at the West end of the well location facing Southwest. The photo illustrates the topsoil pile has been seeded and has good accumulation of vegetation that has been mowed and stabilized by vegetation. Since being mowed it is unclear what the vegetation is, potentially a native seed mix with triticale.



Photo 7. The photo was taken on the well location facing Northeast. The photo illustrates uncovered cellars around the wellheads.



Photo 8. The photo was taken on the well location facing Northwest. The photo illustrates an area where topsoil was removed from the stockpile.