

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403573156

Date Received:

10/26/2023

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

5 of 5 CAs from the FIR responded to on this Form

5 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10433

Name of Operator: LARAMIE ENERGY LLC

Address: 1700 LINCOLN ST STE 3950

City: DENVER State: CO Zip: 80203

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Fischer, Alex

alex.fischer@state.co.us

Arauza, Steven

steven.arauza@state.co.us

Arthur, Denise

denise.arthur@state.co.us

Laramie

cogccnotifications@laramie-energy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 696205144

Inspection Date: 08/04/2023

FIR Submit Date: 08/07/2023

FIR Status: _____

Inspected Operator Information:

Company Name: LARAMIE ENERGY LLC

Company Number: 10433

Address: 1700 LINCOLN ST STE 3950

City: DENVER State: CO Zip: 80203

LOCATION - Location ID: 383264

Location Name: Cascade Creek (CC) Number: 0610-21-41 County: _____

Qtrqr: NENW Sec: 10 Twp: 6S Range: 97W Meridian: 6

Latitude: 39.544325 Longitude: -108.207010

FACILITY - API Number: 05-045-00 Facility ID: 383264

Facility Name: Cascade Creek (CC) Number: 0610-21-41

Qtrqr: NENW Sec: 10 Twp: 6S Range: 97W Meridian: 6

Latitude: 39.544325 Longitude: -108.207010

CORRECTIVE ACTIONS:

1 ☒ CA# 177590

Corrective Action: Clean/remediated soils to Table 915-1 cleanup standards.

Date: 08/04/2023

Response: CA COMPLETED

Date of Completion: 08/08/2023

Spill ID is 484892. Stained soil has been addressed

Operator
Comment:

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with ECMC rules.

2 ☒ CA# 177591

Corrective Action: Comply with Rule 1002.f and Form 2A COAs.

Date: 07/14/2023

This issue is now also being considered a Spill. Contact NW EPS Arauza, or EPS Supervisor Alex Fischer (alex.fischer@state.co.us) for Form 27 remediation, and possible Form 19 Spill reporting requirements, for areas beyond the Working Pad Surface of the Location impacted by drill cutting E&P waste; this issue is being considered for enforcement.

Response: CA COMPLETED

Date of Completion: 08/08/2023

Operator
Comment: Spill ID is 484892

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with ECMC rules.

3 ☒ CA# 177592

Corrective Action: Contact NW EPS Arauza (steven.arauza@state.co.us), or Western EPS Supervisor Alex Fischer (alex.fischer@state.co.us).

Date: 07/14/2023

Response: CA COMPLETED

Date of Completion: 08/08/2023

Operator
Comment: Cuttings have been pushed off of working surface.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with ECMC rules.

4 ☒ CA# 177593

Corrective Action: Comply with Rules 606.c and 1002.c.

Date: 08/04/2023

Response: CA COMPLETED

Date of Completion: 10/25/2023

Operator
Comment: Weeds have been sprayed, Laramie will continue to monitor the Noxious Weeds

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with ECMC rules.

5 ☒ CA# 177594

Corrective Action: Comply with Rule 1002.f; install or repair required stormwater and erosion control BMPs in accordance with good engineering practices.

Date: 08/04/2023

Response: CA COMPLETED

Date of Completion: 10/24/2023

Berms have been repaired.

Operator
Comment:

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with ECMC rules.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Lori Muhr

Signed: _____

Title: Regulatory

Date: 10/26/2023 7:30:42 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403573156	FIR RESOLUTION SUBMITTED
403573200	CA Photos

Total Attach: 2 Files