

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
403579742

Date Received:
11/01/2023

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 7 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Dekam, Eric</u>		<u>edekam@terraep.com</u>
<u>.TEP</u>		<u>COGCCInspectionReports@terraep.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 696205220
Inspection Date: 09/06/2023 FIR Submit Date: 09/07/2023 FIR Status: _____

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC Company Number: 96850
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 311852

Location Name: BOIES RANCH Number: B-19N PAD County: _____
Qtrqtr: SESW Sec: 19 Twp: 2S Range: 97W Meridian: 6
Latitude: 39.857741 Longitude: -108.329080

FACILITY - API Number: 05-103-00 Facility ID: 311852

Facility Name: BOIES RANCH Number: B-19N PAD
Qtrqtr: SESW Sec: 19 Twp: 2S Range: 97W Meridian: 6
Latitude: 39.857741 Longitude: -108.329080

CORRECTIVE ACTIONS:

6 CA# 180448

Corrective Action: Remove risers, and other surface equipment associated with the AL wells remaining on the Location. Date: 09/06/2023

Response: CA COMPLETED Date of Completion: 09/06/2023

Operator Comment: To provide further clarification to FIRR (doc #403533730) submitted on 9/18/23, TEP maintains and operates multiple active producing wells at this location, and the site is not in a final reclaim status. Because these flowlines have potential future uses to support on-going operations at this location, and the status of the subject flowlines is considered to be "out-of-service." Where such "out-of-service" on-location flowlines may be utilized to support current / future operations, the application of OOSLAT is allowed per Rule 1101.a.(3). Once site

operations have been permanently discontinued and the site undergoes final reclamation, such lines will be permanently abandoned in compliance with Rule 1105.

Therefore, since the subject flowlines are considered to be in "out-of-service" status pending potential future use, and the application of OOSLAT to these lines complies with Rule 1101.a.(3).

COGCC Decision: **Not Approved**

COGCC Representative: Equipment associated with abandoned wells require removal pursuant to 1004.a.
CA remains applicable.

OPERATOR COMMENT AND SUBMITTAL

Comment: To provide further clarification to FIRR (doc #403533730) submitted on 9/18/23, TEP maintains and operates multiple active producing wells at this location, and the site is not in a final reclaim status. Because these flowlines have potential future uses to support on-going operations at this location, and the status of the subject flowlines is considered to be "out-of-service." Where such "out-of-service" on-location flowlines may be utilized to support current / future operations, the application of OOSLAT is allowed per Rule 1101.a.(3). Once site operations have been permanently discontinued and the site undergoes final reclamation, such lines will be permanently abandoned in compliance with Rule 1105.

Therefore, since the subject flowlines are considered to be in "out-of-service" status pending potential future use, and the application of OOSLAT to these lines complies with Rule 1101.a.(3).

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Michael Gardner Signed: _____

Title: TEP Environmental Lead Date: 11/1/2023 10:17:20 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
403579742	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files