

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/02/2023

Submitted Date:

11/03/2023

Document Number:

694500605

FIELD INSPECTION FORM

Loc ID 446527 Inspector Name: NEIDEL, KRIS On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10805
Name of Operator: FULCRUM ENERGY OPERATING LLC
Address: 240 SAINT PAUL STREET SUITE 502
City: DENVER State: CO Zip: 80206

Findings:

- 2 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|---------------|--------------|----------------------------|---------|
| Fischer, Alex | | alex.fischer@state.co.us | |
| Blohm, Justin | 520-820-2380 | justin.blohm@fulcrumeo.com | |

General Comment:

ON 11/2/23 C ECMC staff inspected the Spill at the Pintail location. At the time of inspection, weather was dry, overcast and 45 degrees. Crews were inside the Tank Battery secondary containment removing fluid with a Vac truck. Nearly all of the surface of the engineered secondary containment was observed as coated with spilled fluid. No oil was observed weeping or spilled outside of secondary containment. 2 totes were observed near a fired line heater on the south east side of location. The totes were labeled as Ethylene Glycol but had a dark fluid in them. Corrective Actions: Continue with clean up and documentation on the Form 19. Remove or Properly store fluid in chemical totes, RULE 606, 605.h.(3). See attached Photos.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type STORAGE OF SUPL

Comment: near fired heater, on south east side of location there were some stored totes. The totes were labeled as Ethylene Glycol, it was obvious that there is a fluid other than Glycol contained in these totes.

Corrective Action: Remove totes and dispose of fluid appropriately.

Date: 11/17/2023

Overall Good:

Spills:

| Type | Area | Volume |
|------|------|--------|
| | | |

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------|---|
| 694500606 | photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6309237 |