

01072767

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY


NOV 29 1984

Budget Bureau No. 42-2384
COLO. OIL & GAS CONS. COMM.

Land Office Denver

Lease No. 033804(b)

Unit _____



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	<input checked="" type="checkbox"/>	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

April 18, 1966

Well No. 50 is located 1225 ft. from N line and 1425 ft. from W line of sec. 11

SE 1/4 SW 1/4 Sec. 11 IN 102W 6th P.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Rangely Rio Blanco Colorado
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 5423 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

To drill to top of Dakota or oil at a lesser depth.

Will set 500' of 7-inch csg.

Approved 4/19/66
E.R. Haymaker
District Engineer

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Lu Bauer Petroleum Company

Address P.O. Box 87

Rangely, Colorado

By Lu Bauer
Title Owner