



01072759

OIL AND GAS CONSERVATION COMMISSION  
OF THE STATE OF COLORADO  
Room 312, State Services Bldg.  
1525 Sherman Street  
Denver, Colorado 80203



LuBauer Petroleum Co.  
1917 East Washington  
Phoenix, Arizona

July 22, 1966

Gentlemen:

We have not received reports, as checked below, for the following well:

# 50 Gov. SESW 11-1N-102 W Rangely, Rio Blanco

COMMENTS:

Present status please

- ☐ Form 1 Designation of Agent
- ☐ Form 2 Application for Permit to Drill, Deepen, or Plug Back
- ☐ Form 3 Bonding Requirements
- ☒ Form 4 Sundry Notices and Reports on Wells
- ☐ Form 5 Well Completion or Recompletion Report and Log
- ☐ Form 10 Certificate of Clearance
- ☐ Others:

Please submit the above requested reports to this office as soon as possible.

OIL AND GAS CONSERVATION COMMISSION

*D. V. Rogers*

D. V. Rogers, Director

We have just finished drilling this well and are now in the process of putting rods and tubing in it. When well is completed and tested we will file ~~proper~~ forms for completion.  
proper

L.P.G.