

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/30/2023

Submitted Date:

10/31/2023

Document Number:

712700800

**FIELD INSPECTION FORM**Loc ID 325156 Inspector Name: Pattillo, Curtis On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10766

Name of Operator: ARKOMA OPERATIONS LLC

Address: 2121 S COLUMBIA AVE SUITE 101

City: TULSA State: OK Zip: 74114

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

12 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
, General		SJBcompliance@arkomaops.com	All SW Inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214148	WELL	PR	05/19/2003	GW	067-05464	FORD-OLSON UNIT 1	PR

**General Comment:**

SW Compliance Specialist Curtis Pattillo conducted a field inspection of the access road and well location.

Location				
<b>Lease Road:</b>				
Type	Access			
comment:	Gravel surface, access from CR 311.			
Corrective Action	L			Date:
Overall Good: <input checked="" type="checkbox"/>				
<b>Signs/Marker:</b>				
Type	WELLHEAD			
Comment:	Metal sign posted at wellhead.			
Corrective Action:				Date:
Type	OTHER			
Comment:	Warning sign posted at location entrance. Warning sign on meterhouse.			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	24 hour operator contact number and 911 local emergency number posted on well location signage.			
Corrective Action:				Date:
Overall Good: <input checked="" type="checkbox"/>				
<b>Spills:</b>				
Type	Area	Volume		
In Containment: No				
Comment: <input type="text"/>				
<input type="checkbox"/> Multiple Spills and Releases?				
<b>Fencing/:</b>				
Type				
Comment:				
Corrective Action:				Date:
<b>Equipment:</b>				
				corrective date
Type: Flow Line	# 3			
Comment:	3-2" lines from wellhead to separator.			
Corrective Action:				Date:
Type: Gathering Line	# 1			
Comment:	Above ground valve and piping.			
Corrective Action:				Date:
Type: Pig Station	# 1			
Comment:				
Corrective Action:				Date:
Type: Ancillary equipment	# 1			
Comment:	Wellhead			
Corrective Action:				Date:

Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:	2" line from separator to meterhouse. Calibration date 10/4/2023.		
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	Accessible		
Corrective Action:			Date:
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:
Type: Horizontal Separator	# 1		
Comment:			
Corrective Action:			Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	214148	Type:	WELL	API Number:	067-05464	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:				Date:					
BradenHead									
Date of Last Brhd Test:	09/13/2023		Annual Brhd Completed?	Yes					
Last Brhd Test Results	Initial Surf Csg Pressure:	64	Fluid Type:						
	End Surf Csg Pressure:	1							
Comment:									
Corrective Action:				Date:					

### Reclamation - Storm Water - Pit

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass	Ditches	Pass			
Waddles	Fail	Check Dams	Pass			
Berms	Pass	Culverts	Pass			
Check Dams	Fail					
Compaction	Pass	Gravel	Pass			
Rip Rap	Pass	Rip Rap	Pass			

Comment: On north end of location, berms/ditches lead to rip/rap check dams and wattles. Sediment migration has filled and overwhelmed these BMPs. See photo #6.

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 11/15/2023

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403577715	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6303308">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6303308</a>
712700805	INSPECTION PHOTOS	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6303303">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6303303</a>