

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:

403594227

Date Received:

11/13/2023

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 69175

Name of Operator: PDC ENERGY INC

Address: 1099 18TH STREET SUITE 1500

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Tyranny Bergin

970-313-5547

EHSCOGCCInspections@pdce.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 701900989

Inspection Date: 07/15/2023

FIR Submit Date: 08/15/2023

FIR Status: _____

Inspected Operator Information:

Company Name: PDC ENERGY INC

Company Number: 69175

Address: 1775 SHERMAN STREET - STE 3000

City: DENVER State: CO Zip: 80203

LOCATION - Location ID: 305953

Location Name: ALM-67N65W Number: 33NENE County: _____

Qtrqtr: NENE Sec: 33 Twp: 7N Range: 65W Meridian: 6

Latitude: 40.536110 Longitude: -104.661190

FACILITY - API Number: 05-123-

-00

Facility ID: 305953

Facility Name: ALM-67N65W

Number: 33NENE

Qtrqtr: NENE Sec: 33 Twp: 7N Range: 65W Meridian: 6

Latitude: 40.536110 Longitude: -104.661190

CORRECTIVE ACTIONS:

1 CA# 178506

Corrective Action: Comply with Rule 1004.a to remove (regardless of ownership) all debris, abandoned gathering line risers, and flowline risers, and equipment within three months of plugging (3/2/2017) the associated facility.

Date: 08/02/2023

The corrective date is not intended to be the date for which the Operator shall complete the corrective actions but rather the corrective date is the date the location was observed out of compliance.

Response: CA COMPLETED

Date of Completion: 10/31/2023

This is not a riser remaining after plugging activities. This is DCP's isolation valve for the midstream operations remaining downline. This requires the valve to remain for their entire operations and cannot be removed. CA

complete.

--

<u>OPERATOR COMMENT AND SUBMITTAL</u>	

This is not a riser remaining after plugging activities. This is DCP's isolation valve for the midstream operations remaining downline. This requires the valve to remain for their entire operations and cannot be removed. CA complete.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____

Date: 11/13/2023 8:48:46 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

--	--

Total Attach: 0 Files