

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Domestic Tap 35NESW

Location # 323890

Facility # 456905



Photo # 6979 Domestic tap



Photo # 6980 Domestic tap

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Domestic Tap 35NESW

Location # 323890

Facility # 456905



Photo # 6981 Domestic tap



Photo # 6982 Domestic tap

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Domestic Tap 35NESW

Location # 323890

Facility # 456905



Photo # 6983 Domestic tap



Photo # 6984 Domestic tap

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Domestic Tap 35NESW

Location # 323890

Facility # 456905



Photo # 6985 PRV vent line lacks cap



Photo # 6986 PRV vent line lacks cap

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Domestic Tap 35NESW

Location # 323890

Facility # 456905



Photo # 6987 Possible leak on PRV



Photo # 6988 Possible leak on PRV

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Domestic Tap 35NESW

Location # 323890

Facility # 456905



Photo # 6989 Possible leak on PRV

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Domestic Tap 35NESW

Location # 323890

Facility # 456905



Domestic Tap location marked in red. Domestic Tap is located just off the left hand side of lease road approximately 400 yards from the entrance to the BARRETT RMV 16-35 pad location # 323890



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources