



00063313

STATE OF COLORADO
OIL AND GAS CONSERVATION COMMISSION

DEPARTMENT OF NATURAL RESOURCES
SUITE 380 LOGAN TOWER BUILDING
1580 LOGAN STREET
DENVER, COLORADO 80203

WILLIAM R. SMITH
Director
DENNIS R. BICKNELL
Deputy Director

(303) 894-2100

ROY ROMER
Governor

July 27, 1990

Mr. Dan Skeem
Aurawest Capital Corp.
47 West 200 South, Suite 319
Salt Lake City, Utah 84101

Re: Well Status Report

Dear Mr. Skeem,

This letter is in regard to the last field inspection conducted in the area of the Coltharp Lease, sec 1-1N-102W and sec 36-2N-102W. A workover rig was on a hole approximately 100' north of your Coltharp A-2 well without a crew present on June 27, 1990. The Coltharp A-2 still had the lease sign and a steel cap over the surface pipe.

The Sundry notice received on the Coltharp A-2 well stated that a dry hole marker was set on top of the cement plug in the surface pipe. Since the well found did not meet this description I assume that the final cutting (and cementing) of the surface pipe below groundlevel would be done at the same time the well 100' north of the Coltharp A-2 well operations are completed. Update this office on the well north of the A-2.

Status reports are required for the Coltharp A-1, 1485' FWL, 865' FNL sec 1-1N-102W and the Coltharp E-1, 2220' FWL, 120' FNL sec 36-2N-102W.

Yours truly,

Stephan Pott
Sr. Engineer

* Please notify this office when the work has been completed on the wells in question.