

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:

403602049

Date Received:

11/21/2023

FIR RESOLUTION FORM

Overall Status:

CA Summary:

4 of 5 CAs from the FIR responded to on this Form

4 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 7800

Name of Operator: BEREN CORPORATION

Address: 2020 N BRAMBLEWOOD STREET

City: WICHITA State: KS Zip: 67206

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Krystal Heibel

303-817-5217

krystal.heibel@state.co.us

Kay, Michael

316-249-7597

kaym@berexco.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 709100115

Inspection Date: 09/24/2023

FIR Submit Date: 10/03/2023

FIR Status: _____

Inspected Operator Information:

Company Name: BEREN CORPORATION

Company Number: 7800

Address: 2020 N BRAMBLEWOOD STREET

City: WICHITA State: KS Zip: 67206

LOCATION - Location ID: 450327

Location Name: Brewer A Tank Battery Number: _____ County: _____

Qtrqtr: SESE Sec: 15 Twp: 8N Range: 53W Meridian: 6

Latitude: 40.654909 Longitude: -103.279013

FACILITY - API Number: 05-075- -00 Facility ID: 450327

Facility Name: Brewer A Tank Battery Number: _____

Qtrqtr: SESE Sec: 15 Twp: 8N Range: 53W Meridian: 6

Latitude: 40.654909 Longitude: -103.279013

CORRECTIVE ACTIONS:

1 CA# 182905

Corrective Action: Repair or install berms or other secondary containment devices per Rule 912.d.(1).

Date: 10/24/2023

Response: CA COMPLETED

Date of Completion: 10/06/2023

Operator
Comment:

Pumper filled in and repaired all holes in berms. See attached Figures 1-7.

COGCC Decision: _____

COGCC
Representative:

2 CA# 182906

Corrective Action: Inspect, maintain and repair tanks to comply with rule 609.b.

Date: 11/03/2023

Response: CA COMPLETED

Date of Completion: 10/06/2023

Operator
Comment:

Burrows underneath tanks filled in and repaired. See attached Figure 2.

COGCC Decision:

COGCC
Representative:

4 CA# 182908

Corrective Action: Comply with Rule 606

Date: 10/11/2023

Response: CA COMPLETED

Date of Completion: 10/06/2023

Operator
Comment:

Picked up water bottle on location. See attached Figure 1.

COGCC Decision:

COGCC
Representative:

5 CA# 182909

Corrective Action: Comply with Rule 606

Date: 10/11/2023

Response: CA COMPLETED

Date of Completion: 10/06/2023

Operator
Comment:

Spare chemical drum rack removed from location by foreman.

COGCC Decision:

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Operator has completed 4 of the 5 corrective actions. We have ordered what we need to bring the tank signs into compliance. Another FIRR will be submitted once the sign work is done.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Michael Kay

Signed:

Title: Division Engineer

Date: 11/21/2023 10:40:50 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

403602822	Water bottle picked up from location.
-----------	---------------------------------------

403602823	Burrows underneath tanks filled in and repaired.
403602824	Burrows filled in and repaired.
403602825	Burrows filled in and repaired.
403602827	Burrows filled in and repaired.
403602830	Burrows filled in and repaired.
403602831	Burrows filled in and repaired.

Total Attach: 7 Files