

Storm Water Management and Erosion control

Location Name: MUSTANG RESOURCES LLC RULISON FEDERAL 3-94-7S-94W Pad

Location ID: 322308



Location Overview: Location is within High Priority/Density/Black Bear Habitat areas.

Section/Township/Range: 3 7S94W



Storm water Management and Erosion control

Location Name: MUSTANG RESOURCES LLC RULISON FEDERAL 3-94-7S-94W Pad

Location ID: 322308



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.

Storm water Management and Erosion control

Location Name: MUSTANG RESOURCES LLC RULISON FEDERAL 3-94-7S-94W Pad

Location ID: 322308



Photo # 7608 Lack of stabilization/compaction



Photo # 7609 Lack of stabilization/compaction

Storm water Management and Erosion control

Location Name: MUSTANG RESOURCES LLC RULISON FEDERAL 3-94-7S-94W Pad

Location ID: 322308



Photo # 7610 Lack of stabilization/compaction

Photo # 7611 Lack of stabilization/compaction

Storm water Management and Erosion control

Location Name: MUSTANG RESOURCES LLC RULISON FEDERAL 3-94-7S-94W Pad

Location ID: 322308




Photo # 7612 Lack of stabilization/compaction



Photo # 7613 Lack of stabilization/compaction

Storm water Management and Erosion control

Location Name: MUSTANG RESOURCES LLC RULISON FEDERAL 3-94-7S-94W Pad

Location ID: 322308



Photo # 7614 Lack of stabilization/compaction



Photo # 7615 Lack of stabilization/compaction

Storm water Management and Erosion control

Location Name: MUSTANG RESOURCES LLC RULISON FEDERAL 3-94-7S-94W Pad

Location ID: 322308



Photo # 7616 Lack of stabilization/compaction



Photo # 7617 Erosion & transport of sediment off location

Storm water Management and Erosion control

Location Name: MUSTANG RESOURCES LLC RULISON FEDERAL 3-94-7S-94W Pad

Location ID: 322308



Photo # 7618 Erosion & transport of sediment off location

Photo # 7619 Erosion & transport of sediment off location

Storm water Management and Erosion control

Location Name: MUSTANG RESOURCES LLC RULISON FEDERAL 3-94-7S-94W Pad

Location ID: 322308



Nov 27, 2023 at 11:50:03 AM



Nov 27, 2023 at 11:50:03 AM

Photo # 7620 Erosion & transport of sediment off location

Photo # 7621 Erosion & transport of sediment off location

Storm water Management and Erosion control

Location Name: MUSTANG RESOURCES LLC RULISON FEDERAL 3-94-7S-94W Pad

Location ID: 322308



Photo # 7622 Erosion & transport of sediment off location



Photo # 7623 Erosion & transport of sediment off location