

Operator: CIVITAS NORTH LLC
Location Name: BASHOR-69N60W 18SWNW
Loc ID: 323023
Inspection: 708200677



Exhibit A



Exhibit B

CA: This location does not comply with Rule 1003. During this inspection, it was observed that areas within the interim reclaimed portions are not progressing towards reclamation standards with evidence of undesirable vegetation (e.g. kochia and Russian thistle) and areas of non-uniform vegetation cover resulting in bare/exposed soils. Additional reclamation activities are required. Operator submitted this location on Form 6A (doc no 403361744) Out of Service Designation and Plugging List, however, this location stills need to comply with ECMC Rules and Regulations prior to plugging and abandonment. Comply with Rule 1003. The location will remain out of compliance until corrective action has been resolved.

CA Resolution: Operator reported that the Field has appropriately complied with Rule 1003 by addressing/clearing all tumble weeds, mowing the location, prepping location and drilling/re-seeding area, and installing straw mulch. Field has also cleaned up trash and weeds that were identified around the equipment.