

State of Colorado  
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:

403628540

Date Received:

12/18/2023

## FIR RESOLUTION FORM

**Overall Status:**

**CA Summary:**

3 of 3 CAs from the FIR responded to on this Form

0 CA Completed  
3 Factual Review Request

### OPERATOR INFORMATION

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

**Additional Operator Contact:**

Contact Name

Phone

Email

Baker, Brandon

bbaker@terraep.com

TEP

COGCCInspectionReports@terraep.com

Dekam, Eric

edekam@terraep.com

Heil, John

john.heil@state.co.us

### COGCC INSPECTION SUMMARY:

FIR Document Number: 696205469

Inspection Date: 12/11/2023

FIR Submit Date: 12/14/2023

FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC

Company Number: 96850

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

### LOCATION - Location ID: 420224

Location Name: T & T Assoc. LTD Number: PA 21-7 County: \_\_\_\_\_

Qtrqtr: Lot 2 Sec: 7 Twp: 7S Range: 95W Meridian: 6

Latitude: 39.456476 Longitude: -108.043846

### FACILITY - API Number: 05-045- -00 Facility ID: 420224

Facility Name: T & T Assoc. LTD Number: PA 21-7

Qtrqtr: Lot 2 Sec: 7 Twp: 7S Range: 95W Meridian: 6

Latitude: 39.456476 Longitude: -108.043846

### CORRECTIVE ACTIONS:

1 CA# 189205

Corrective Action: Install proper signage

Date: 09/15/2023

Response: FACTUAL REVIEW REQUEST

Basis for Review: Corrective action dates are not attainable

The PA 21-7 location has been in operation since 2011. The PA 21-7 location predates the current ECMC Rule

Operator Comment: 605, "Signage Requirements for Oil and Gas Locations" (dated January 15, 2021) which requires an entrance sign be posted at all NEW oil and gas locations. TEP maintains that the current regulation does not apply to this location since the PA 21-7 is not a NEW location (i.e., constructed after enactment of the January 15, 2021 rules).

Inspector Trujillo states: "Inspection #707800523 observed that signage at the Location entrance had not been posted. Inspection required Operator to install proper signage. It was observed in this inspection that signage at the location entrance remains missing. This CA remains applicable." TEP believes that this CA was not a valid CA at the time of the inspection conducted on 09/15/23, and remains an invalid CA today.

Please provide a valid citation that would require posting additional signage at the entrance to the location.

COGCC Decision: \_\_\_\_\_

COGCC Representative: \_\_\_\_\_

**2** CA# 189206

Corrective Action: Comply with Rule 911.a

Date: 12/11/2023

Response: FACTUAL REVIEW REQUEST

Basis for Review: Corrective action dates are not attainable

Operator Comment: Inspector Trujillo conducted the inspection on 12/11/23. The FIR and corrective action were sent to TEP on 12/13/23 with the corrective action due date of 12/11/23. The inspection report was not submitted or received by TEP until two days AFTER the corrective action due date had already expired. Therefore, the corrective action date for this CA was not attainable. An attainable / reasonable CA due date is requested.

COGCC Decision: \_\_\_\_\_

COGCC Representative: \_\_\_\_\_

**3** CA# 189207

Corrective Action: Comply with Rule 606.

Date: 12/11/2023

Response: FACTUAL REVIEW REQUEST

Basis for Review: Corrective action dates are not attainable

Operator Comment: Inspector Trujillo conducted the inspection on 12/11/23. The FIR and corrective action were sent to TEP on 12/13/23 with the corrective action due date of 12/11/23. The inspection report was not submitted or received by TEP until two days AFTER the corrective due date had already expired. Therefore, the corrective action date for this CA was not attainable. An attainable / reasonable CA due date is requested.

It should be noted that the PA 21-7 location is located immediately adjacent to (and downwind from) a newly constructed McDonalds Restaurant and 24-hour truck-stop. The single Egg McMuffin wrapper caught on the fence around the wells as noted in Inspector Trujillo's inspection report, most likely blew in from the adjoining commercial property. The Egg McMuffin wrapper has been picked up and properly disposed of by TEP personnel. It should be noted that TEP personnel routinely pick up wind-blown trash that is irresponsibly discarded by patrons of the adjoining property and which blows over onto our oil and gas location.

COGCC Decision: \_\_\_\_\_

COGCC Representative: \_\_\_\_\_

**OPERATOR COMMENT AND SUBMITTAL**

Comment: Factual Review Requested for the following reasons:

- 1) Corrective Action due dates are not attainable for all three of the Corrective Actions noted on this inspection report. All CA due dates were expired before the FIR was event sent to TEP.
- 2) There is no regulatory basis for CA #189205.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Michael Gardner

Signed: \_\_\_\_\_

Title: TEP Environmental Lead

Date: 12/18/2023 4:32:47 PM

## ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

**Document Number**

**Description**

--	--

Total Attach: 0 Files