

Henderson 1

ECMC Inspection 696305448

Corrective Action: Install sign to comply with Rule 605.h

Operator Response: Sign has been installed



Henderson 1

ECMC Inspection 696305448

Corrective Action: Install sign to comply with Rule 605.e

Operator Response: Emergency number has been replaced

