



November 23, 1964

Mr. Millard Huey
Box 25
Fort Morgan, Colorado

Dear Mr. Huey:

On November 15, 1964, you filed a report on remedial work on the #1 Huey well located in the NE NE, Section 12, Township 2 North, Range 57 West, Morgan County, Colorado. You had previously advised that 2-7/8 inch pipe had been run and perforated from 5432 to 40. Your report of the 15th indicated "J" sand water being produced through "D" sand perforations, which would indicate that the 2-7/8 inch pipe had not been cemented.

Prior to approving the report of this remedial work, we must be advised as to the completion method.

Very truly yours,

OIL AND GAS CONSERVATION COMMISSION
OF THE STATE OF COLORADO

William R. Smith, Deputy Director

WRS:lf

✓