

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/19/2023

Submitted Date:

12/19/2023

Document Number:

708902565**FIELD INSPECTION FORM**Loc ID 323790 Inspector Name: Smelser, Wayne On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: 1058 COUNTY ROAD 215City: PARACHUTE State: CO Zip: 81635**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**6 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
456910	Domestic Tap	AC	08/28/2018		-	Domestic Tap 34NENW	AC

**General Comment:****CECMC Inspection Report Summary**

On 12/19/2023 at approximately 14:06 hours, I, Compliance Specialist, Wayne Smelser  
 Conducted a domestic tap inspection at TEP ROCKY MOUNTAIN LLC Domestic Tap 34NENW  
 Location # 323790 Facility # 456910 in Garfield County Colorado.  
 While there, I observed the domestic tap is derived from TEP sales line.

During this inspection the following compliance issues were observed:

1. Equipment - PRV vent line lacks cap with a CA date of 12/26/2023

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This is a summary of inspection report

**Location****Lease Road:**

Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☐**Emergency Contact Number:**

Comment:		Date:	
Corrective Action:			

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Other	# 1		corrective date
Comment:	PRV vent line lacks cap		
Corrective Action:	Vents on pressure safety devices will be designed to be clear and free of debris and water at all times.		Date: 12/26/2023
Type: Other	# 1		
Comment:	Domestic tap		
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	456910	Type:	Domestic Tap	API Number:	-	Status:	AC	Insp. Status:	AC
Producing Well									
Comment:	While there, I observed the domestic tap is derived from TEP's sales line. The pressure is regulated by a big Joe regulator. Following regulator there's a fluid knock out equipped with a PRV, following the knock out there's a little Joe regulator & after the regulator there's an in line odorizer. Fittings appear to be adequately sized to handle the maximum operating pressures of the regulators.								
Corrective Action:								Date:	

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [Domestic tap inspection only](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<a href="#">Please refer to Equipment for observed compliance issue.</a>	smelserw	12/19/2023
<a href="#">Domestic tap inspection only</a>		

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403631060	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6362716">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6362716</a>
708902566	Inspection 708902565 photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6362714">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6362714</a>