

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403221762

Date Received:
11/08/2022

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10133
Name of Operator: HILCORP ENERGY COMPANY

Address: P O BOX 61229

City: HOUSTON State: TX Zip: 77208

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

General

FarmingtonRegulatoryTechs@hilcorp.com

Labowskie, Steve

steve.labowskie@state.co.us

COGCC INSPECTION SUMMARY:

FIR Document Number: 702500708

Inspection Date: 10/31/2022

FIR Submit Date: 10/31/2022

FIR Status: _____

Inspected Operator Information:

Company Name: HILCORP ENERGY COMPANY

Company Number: 10133

Address: P O BOX 61229

City: HOUSTON State: TX Zip: 77208

LOCATION - Location ID: 326653

Location Name: HUBER-N35N8W Number: 23SWSW County: LA PLATA

Qtrqr: SWS Sec: 23 Twp: 35N Range: 8W Meridian: N
W

Latitude: 37.285220 Longitude: -107.719430

FACILITY - API Number: 05-067- -00 Facility ID: 261385

Facility Name: HUBER Number: 2-23

Qtrqr: SWS Sec: 23 Twp: 35N Range: 8W Meridian: N
W

Latitude: 37.285220 Longitude: -107.719430

CORRECTIVE ACTIONS:

1 ☒ CA# 165804

Corrective Action: All unused equipment must be returned to use or stored off location per rule 606.

Date: 11/08/2022

Response: CA COMPLETED

Date of Completion: 11/02/2022

Operator Comment: Door and telemetry have been removed. See attached photos.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

2 ☒ CA# 165805

Corrective Action: Implement or modify BMPs for improved material handling and spill prevention per rule 1002.f.(2)B.

Date: 11/15/2022

Response: CA COMPLETED

Date of Completion: 11/02/2022

Operator
Comment: Added a berm around the day tank for the PU. See attached photos.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

3 ☒ CA# 165806

Corrective Action: Install proper guy line markers per Rule 1003.a

Date: 11/15/2022

Response: CA COMPLETED

Date of Completion: 11/03/2022

Operator
Comment: Rig anchor is marked. See attached photos.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Priscilla Shorty

Signed: _____

Title: OperationsRegulatory Tech

Date: 11/8/2022 7:08:02 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

403221762	FIR RESOLUTION SUBMITTED
403221763	Huber 2-23 Resolved Photos

Total Attach: 2 Files