

FORM
INSPRev
X/20

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/15/2023

Submitted Date:

12/28/2023

Document Number:

713900195

FIELD INSPECTION FORM

Loc ID 429060 Inspector Name: Hansen, Logan On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 8960
Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY
Address: 410 17TH STREET SUITE #1400
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 6 Number of Comments
5 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Binschus, Chris		chris.binschus@state.co.us	
,		inspections@civiresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
429060	LOCATION	AC			-	North Platte I-24 Pad	RI
429061	WELL	PR	04/01/2021	OW	123-35663	North Platte 24-21-24HZ	RI
429691	WELL	PR	10/01/2019	OW	123-35867	North Platte J-F-24HZ	RI
437398	WELL	PR	03/01/2023	OW	123-39517	North Platte E-A-24HNC	RI
437399	WELL	PR	06/01/2023	OW	123-39518	North Platte O-K-24HC	RI
437400	WELL	PR	10/01/2019	OW	123-39519	North Platte O-K-24HNB	RI
437401	WELL	PR	10/01/2019	OW	123-39520	North Platte E-A-24HNA	RI

General Comment:

This is an Interim Reclamation and Stormwater Inspection.

Location

Overall Good:

Signs/Marker:

Type			
Comment:	Tank labels illegible or missing. See inspection photos for details.		
Corrective Action:	Replace tank labels per Rule 605.	Date:	12/15/2023

Emergency Contact Number:

Comment:	<input type="text"/>	Date:	<input type="text"/>
Corrective Action:	<input type="text"/>		

Good Housekeeping:

Type	WEEDS		
Comment:	Weed debris in the form of tumbleweeds were observed along the entirety of the perimeter fence line and growing in the interim areas. Tumbleweeds are a troublesome annual non-native weed that easily breaks off at the stem. Operator failed to control and manage weeds to prevent weed waste and prevent the spread of seeds onto adjacent lands.		
Corrective Action:	Comply with Rule 606 to remove weed debris.	Date:	12/15/2023

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 429060 Type: LOCATION API Number: - Status: AC Insp. Status: RI

Facility ID: 429061 Type: WELL API Number: 123-35663 Status: PR Insp. Status: RI

Facility ID: 429691 Type: WELL API Number: 123-35867 Status: PR Insp. Status: RI

Facility ID: 437398 Type: WELL API Number: 123-39517 Status: PR Insp. Status: RI

Facility ID: 437399 Type: WELL API Number: 123-39518 Status: PR Insp. Status: RI

Facility ID: 437400 Type: WELL API Number: 123-39519 Status: PR Insp. Status: RI

Facility ID: 437401 Type: WELL API Number: 123-39520 Status: PR Insp. Status: RI

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: RANGELAND

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____ Fail _____

Comment **This location does not comply with Reclamation rules. Rule 1002.c. states all stockpiled soils shall be protected from degradation due to contamination, compaction and, to the extent practicable, from wind and water erosion during drilling and production operations. Best management practices to prevent weed establishment and to maintain soil microbial activity shall be implemented.**
Topsoil stockpile has significant weed cover- Russian thistle and Kochia- with no perennial vegetation that would compete with the weedy vegetation and generally work to decrease weed growth.

Corrective Action **Best management practices to prevent weed establishment shall be implemented. Control, manage, and prevent weedy, annual vegetation on all topsoil stockpiles. If reseeding is an option for long-term protection and stabilization of topsoil, then the next favorable seeding opportunity shall be conducted.**

Date **12/15/2023**

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____
 1003c. Compacted areas have been cross ripped? _____
 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
 Cuttings management: _____
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
 Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation Fail

1003e. INTERIM VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____ F _____

Comment It appears the operator has reduced the disturbance to the areas only needed for production operations. However, interim areas are dominated by russian thistle and bare soil throughout the well location, the northern area of the well location is growing Colorado noxious weed list C species Puncturevine and the topsoil stockpile is dominated by russian thistle and bare soil with evidence of vehicle tracking throughout the interim areas.

Corrective Action Perform reclamation in accordance to Rule 1003. Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of reference area levels. Use a seed mixture requested by the surface owner, or a mixture prescribed by the local county NRCS. Ensure erosion controls are implemented to stabilize the seeded soil, and continue to monitor and manage this site until the location meets Rule 1003 standards, including stormwater and weed management.

Date 12/15/2023

Overall Interim Reclamation Fail

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: RANGELAND

Reminder: _____

Comment:

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

Comment:

Corrective Action:

Date _____

Overall Final Reclamation

Well Release on Active Location

Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: This location does not comply with Rule 1002.f. Sediment traps around the perimeter of the well location are overgrown with tumbleweeds and unconsolidated with straw wattles being degraded and rendered ineffective.

Corrective Action: The operator shall repair installed BMP's per Rule 1002.f.

Date: 12/15/2023

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403638958	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6374918
713900196	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6374871