

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:

403643891

Date Received:

01/04/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 8960

Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY LLC

Address: 555 17TH STREET SUITE 3700

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Luke Kelly

970-939-6353

lkelly@civiresources.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 697505024

Inspection Date: 12/14/2023

FIR Submit Date: 12/26/2023

FIR Status: _____

Inspected Operator Information:

Company Name: BONANZA CREEK ENERGY OPERATING COMPANY LLC

Company Number: 8960

Address: 410 17TH STREET SUITE #1400

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 440344

Location Name: Crow Valley Number: 31-18 Pad County: _____

Qtrqtr: NENE Sec: 18 Twp: 7N Range: 62W Meridian: 6

Latitude: 40.580403 Longitude: -104.359985

FACILITY - API Number: 05-123-

-00

Facility ID: 440344

Facility Name: Crow Valley Number: 31-18 Pad

Qtrqtr: NENE Sec: 18 Twp: 7N Range: 62W Meridian: 6

Latitude: 40.580403 Longitude: -104.359985

CORRECTIVE ACTIONS:

1 CA# 189531

Corrective Action: Comply with Rule 1004. Reseed disturbance areas using a seed mixture requested by the surface owner, or a mixture prescribed by the local county NRCS. Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of reference area levels. Ensure erosion controls are implemented to stabilize the seeded soil. Operator shall continue to monitor and manage this site until the location meets Rule 1004 standards, including stormwater and weed management.

Date: 12/14/2023

Response: CA COMPLETED

Date of Completion: 11/08/2023

ECMC Inspector noted that they were unable to access the site and used historical data to assist with the

Operator Comment:	inspection. Operator then reported that the location has been reclaimed (re-seeded and bare areas addressed) and shared photos from the EcoPoint Assessment completed on November, 8th 2023 to show that the location is in compliance with Rule 1004.
COGCC Decision:	
COGCC Representative:	

<u>OPERATOR COMMENT AND SUBMITTAL</u>	
Comment:	CA follow-up has been completed for this location.
I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.	
Print Name: Ashley Noonan	Signed:
Title: Sr Regulatory Analyst	Date: 1/4/2024 12:24:00 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403643892	Inspection Resolution Report

Total Attach: 1 Files