

COLORADO

00250984

## AS CONSERVATION COMMISSION

## FIELD INSPECTION REPORT

RECEIVED

SEP 7 1995

☐ NOTICE OF UNSATISFACTORY INSPECTION☒ NOTICE OF SATISFACTORY INSPECTION1120 Lincoln Street, Suite 801  
Denver, CO 80203  
(303)894-2100

API No. 05- 075 - 06523

LEASE NAME: Henderson 4

LOCATION: SENW 18-9N-53

OPERATOR: Walsh

DATE: 8-28-95

INSPECTOR: Ed Brinkley

Insp. Type: ID

Insp. Status: 51

PA: Y N

Pass/Fail: P F

Viol.: Y N

NOV: Y N

## INSPECTION ITEM

## COMMENTS

## INPUT

Well ID Signs (Rule 210)	Update	
Pits (Reserve/Production) (Rule 902, 903, 904)		
Fences (Rule 604.C.(3), 1003.A)		
Tank Battery Equipment (Rule 604)		
Fire Walls/Berms/Dikes (Rule 604)		
General Housekeeping (Rule 603.G)	OK	
Spills (Oil/Water) (Rule 908)		
Bradenhead (Rule 207)		
Drilling Well/Workover (Rule 315)		
Surface Rehabilitation (Rule 317)		
Miscellaneous	File form 10 - Change of operator	

## CORRECTIVE ACTION REQUIRED:

Date Corrective Action Required By:

Date Remedied:

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.

White - File Green - Operator Canary - Well Site