

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:

403655907

Date Received:

01/17/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10694

Name of Operator: PROVIDENCE OPERATING LLC DBA POCO OPERATING

Address: 16400 DALLAS PARKWAY SUITE 400

City: DALLAS State: TX Zip: 75428

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Brown, Devin

dbrown@providence-energy.com

Grimes, Meghan

mgrimes@providence-energy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 707901183

Inspection Date: 12/18/2023

FIR Submit Date: 12/18/2023

FIR Status: _____

Inspected Operator Information:

Company Name: PROVIDENCE OPERATING LLC DBA POCO OPERATING

Company Number: 10694

Address: 16400 DALLAS PARKWAY SUITE 400

City: DALLAS State: TX Zip: 75428

LOCATION - Location ID: 441625

Location Name: Long Number: 22-B Pad County: WELD

Qtrqtr: NENW Sec: 22 Twp: 1N Range: 65W Meridian: 6

Latitude: 40.043450 Longitude: -104.650920

FACILITY - API Number: 05-123-00 Facility ID: 441802

Facility Name: Long Number: 22-15-6NCH

Qtrqtr: NENW Sec: 22 Twp: 1N Range: 65W Meridian: 6

Latitude: 40.043450 Longitude: -104.650920

CORRECTIVE ACTIONS:

1 CA# 189275

Corrective Action:

Date: 01/18/2024

Out-of-Service Status means a flowline or crude oil transfer line that is associated with an inactive well or the operator has ceased normal operations. For an out of service line, the operator must: A. Isolate or disconnect it from sources of oil, condensate, produced water, or natural gas; B. Evacuate all hydrocarbons and produced water to ensure the line is safe and inert and depressurize the line; and C. apply OOSLAT

Response: CA COMPLETED

Date of Completion: 12/19/2023

Operator Comment: Out of service lines have been removed.

COGCC Decision:

COGCC Representative:

2 CA# 189276

Corrective Action: Properly dispose of oily waste in accordance with 905.e

Date: 01/18/2024

Response: CA COMPLETED

Date of Completion: 12/19/2023

Operator Comment: Stain cleaned up

COGCC Decision:

COGCC Representative:

3 CA# 189277

Corrective Action: Install sign to comply with Rule 605.e.

Date: 01/18/2024

Response: CA COMPLETED

Date of Completion: 01/02/2024

Operator Comment: Sign has been replaced and attached.

COGCC Decision:

COGCC Representative:

4 CA# 189278

Corrective Action: Comply with rule 606

Date: 01/18/2024

Response: CA COMPLETED

Date of Completion: 12/19/2023

Operator Comment: Door removed

COGCC Decision:

COGCC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Resolution photos are attached.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Meghan Grimes

Signed: _____

Title: VP of Regulatory Affairs

Date: 1/17/2024 2:11:49 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

403657493	Resolution photos
-----------	-------------------

Total Attach: 1 Files