

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/10/2024

Submitted Date:

01/18/2024

Document Number:

709400721**FIELD INSPECTION FORM**

Loc ID 459907 Inspector Name: WOLD, REED On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 69175Name of Operator: PDC ENERGY INCAddress: 1099 18TH STREET SUITE 1500City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**3 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
		randythweatt@chevron.com	

General Comment:

This is an interim and stormwater inspection for wells and associated tank battery on site. Corrective actions observed during inspection include weeds (kochia & russian thistle) and stormwater erosion.

LocationOverall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	WEEDS		
Comment:	Failure to control and manage weeds to prevent weed waste and prevent the spread of seeds onto adjacent lands.		
Corrective Action:	Comply with Rule 606.c. The corrective date is not intended to be the date for which the Operator shall complete the corrective actions but rather the corrective date the location was observed out of compliance.		Date: <u>01/10/2024</u>

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Stormwater erosion along side access road and on the south side of well pad.

Corrective Action: Comply with Rule 1002.f. The corrective date is not intended to be the date for which the Operator shall complete the corrective actions but rather the corrective date the location was observed out of compliance.

Date: 01/10/2024

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
709400723	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6398738