

Operator: Civitas North
Location Name: Wade 8-59 17 Pad
Loc ID: 484554
Inspection: 708200892



Exhibit A



Exhibit B



Exhibit C



Exhibit D



Exhibit E



Exhibit F



Exhibit G



Exhibit H



Exhibit I

CA: This location does not comply with Rule 1002.b. During this inspection, it was observed that the access road did not appear to have the topsoil salvaged. Additionally, it appears that topsoil was used as fill material at culvert crossings. Refer to attached inspection photos. Comply with Rule 1002.b. Operator shall ensure all topsoil has been salvaged from the Date access road, including any topsoil used as fill material. The location will remain out of compliance until the corrective action has been resolved.

CA Resolution: Topsoil has been salvaged to comply with Rule 1002.b.