

State of Colorado Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
403664414

Date Received:
02/01/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:
13 of 13 CAs from the FIR responded to on this Form
13 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 3104
Name of Operator: ANSCHUTZ EXPLORATION CORP
Address: 555 17TH ST STE 2400
City: DENVER State: CO Zip: 80202
Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Lindsey Organ</u>		<u>lindsey.organ@aec-denver.com</u>
<u>Burchett, Kirby</u>		<u>kirby.burchett@state.co.us</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 696205473
Inspection Date: 12/18/2023 FIR Submit Date: 12/19/2023 FIR Status: _____

Inspected Operator Information:

Company Name: ANSCHUTZ EXPLORATION CORP Company Number: 3104
Address: 555 17TH ST STE 2400
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 430927

Location Name: BHR Number: J22-397 County: _____
Qtrqtr: NWSE Sec: 22 Twp: 3N Range: 97W Meridian: 6
Latitude: 40.212032 Longitude: -108.259757

FACILITY - API Number: 05-103-00 Facility ID: 430927

Facility Name: BHR Number: J22-397
Qtrqtr: NWSE Sec: 22 Twp: 3N Range: 97W Meridian: 6
Latitude: 40.212032 Longitude: -108.259757

CORRECTIVE ACTIONS:

1 CA# 189305

Corrective Action: Stop leak. Securely fasten all valves, pipes, fittings, and Production Facilities. Ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e. Date: 12/18/2023
Clean/remediate impacts/stained soils to Table 915-1 cleanup concentrations.

Response: CA COMPLETED Date of Completion: 12/20/2023

Leak was stopped. Form 19 reportable spill has been submitted under document #403632910. Project will proceed under spill ID: 485791. Investigation and cleanup of spill is ongoing. Upon completion of cleanup,

Operator Comment: corrective measures including lined containment will be installed around riser.

COGCC Decision: _____

COGCC Representative: _____

2 CA# 189306

Corrective Action: Remove and properly dispose fluids.

Date: 12/18/2023

Response: CA COMPLETED

Date of Completion: 12/20/2023

Operator Comment: Fluid in catch buckets has been removed.

COGCC Decision: _____

COGCC Representative: _____

3 CA# 189307

Corrective Action: Clean/remediate impacts/stained soils to Table 915-1 cleanup concentrations.

Date: 12/18/2023

Response: CA COMPLETED

Date of Completion: 01/18/2024

Operator Comment: Stained gravel inside lined secondary containment has been removed and replaced with clean gravel. Cumulative impacts of cleanup did not exceed 10 cubic yards or exceed 5BBLs of produced fluids.

COGCC Decision: _____

COGCC Representative: _____

4 CA# 189308

Corrective Action: Stop leak. Securely fasten all valves, pipes, fittings, and Production Facilities. Ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.

Date: 12/18/2023

Response: CA COMPLETED

Date of Completion: 12/18/2023

Operator Comment: Leak was stopped and recycling line has been repaired and impacted gravel inside secondary containment has been removed. Equipment will be inspected at regular intervals to ensure it is in proper working condition.

COGCC Decision: _____

COGCC Representative: _____

5 CA# 189309

Corrective Action: Comply with Rule 606.d

Date: 12/18/2023

Response: CA COMPLETED

Date of Completion: 12/28/2023

Operator Comment: Trash and debris has been removed from the location.

COGCC Decision: _____

COGCC Representative: _____

6 CA# 189310

Corrective Action: All loadlines will be bullplugged or capped.

Date: 12/18/2023

Response: CA COMPLETED

Date of Completion: 12/20/2023

Operator Comment: Loadlines were capped.

COGCC Decision: _____

COGCC Representative: _____

7 CA# 189311

Corrective Action: Comply with Rule 606.a

Date: 12/18/2023

Response: CA COMPLETED

Date of Completion: 12/28/2023

Operator Comment: Equipment and unused equipment was removed from the location.

COGCC Decision: _____

COGCC Representative: _____

8 CA# 189312

Corrective Action: Install or repair wildlife protection equipment.

Date: 12/18/2023

Response: CA COMPLETED

Date of Completion: 01/19/2024

Operator Comment: Wildlife netting was installed on tank containment.

COGCC Decision: _____

COGCC Representative: _____

9 CA# 189313

Corrective Action: Comply with Rule 605.e

Date: 12/18/2023

Response: CA COMPLETED

Date of Completion: 01/19/2024

Operator Comment: Tank battery signage has been updated with correct operator information

COGCC Decision: _____

COGCC Representative: _____

10 CA# 189314

Corrective Action: Comply with Rule 605.d

Date: 12/18/2023

Response: CA COMPLETED

Date of Completion: 01/19/2024

Operator Comment: Signage at the wellhead has been updated with correct operator information.

COGCC Decision: _____

COGCC Representative: _____

11 CA# 189315

Corrective Action: Comply with Rules 1002.c, 1003.f and 606.c. Ongoing weed management required until site receives a passing final reclamation inspection.

Date: 12/18/2023

Response: CA COMPLETED

Date of Completion: 08/02/2023

Operator Comment: Weeds were sprayed on location on 8/2/2023. Enhanced weed management will be completed Spring - Fall 2024.

COGCC Decision: _____

COGCC Representative: _____

12 CA# 189316

Corrective Action: Comply with Rule 1003.b- conduct interim reclamation on the Location including, but not limited to, compaction alleviation, recontouring/regrading, replacement of topsoil and revegetation activities on areas not needed for production. Ensure the seed mixture used is provided by the Surface Owner, or Location Soil Conservation Service. BMPs to stabilize the seeded soils will be required upon completion of revegetation activities. Continue to monitor and manage interim areas until Location receives a passing final reclamation inspection.

Date: 12/18/2023

Response: CA COMPLETED

Date of Completion: 01/18/2024

Operator Comment: Interim reclamation will be conducted in 2024. Interim reclamation plan and timing will be submitted by Form 4 Sundry Notice -- Interim Reclamation.

COGCC Decision: _____

COGCC Representative: _____

13 CA# 189317

Corrective Action: Install or repair spill prevention and containment BMPs.

Date: 12/18/2023

Response: CA COMPLETED

Date of Completion: 01/18/2024

Operator Comment: Glycol containment has been replaced with functioning containment.

COGCC Decision: _____

COGCC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: _____

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Lindsey Organ

Signed: _____

Title: Compliance Supervisor

Date: 2/1/2024 3:12:34 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

--	--

Total Attach: 0 Files