

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
403664415

Date Received:
02/01/2024

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

5 of 5 CAs from the FIR responded to on this Form

5 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 3104
Name of Operator: ANSCHUTZ EXPLORATION CORP
Address: 555 17TH ST STE 2400
City: DENVER State: CO Zip: 80202

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Andrews, Doug</u>		<u>doug.andrews@state.co.us</u>
<u>Organ, Lindsey</u>		<u>lindsey.organ@aec-denver.com</u>
<u>Noto, John</u>		<u>john.noto@state.co.us</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 696205471
Inspection Date: 12/18/2023 FIR Submit Date: 12/19/2023 FIR Status: _____

Inspected Operator Information:

Company Name: ANSCHUTZ EXPLORATION CORP Company Number: 3104
Address: 555 17TH ST STE 2400
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 484545

Location Name: Coyote Fed Number: 0397-14 County: _____
Qtrqr: NWN Sec: 14 Twp: 3N Range: 97W Meridian: 6
W
Latitude: 40.235181 Longitude: -108.253230

FACILITY - API Number: 05-081- -00 Facility ID: 484545

Facility Name: Coyote Fed Number: 0397-14
Qtrqr: NWN Sec: 14 Twp: 3N Range: 97W Meridian: 6
W
Latitude: 40.235181 Longitude: -108.253230

CORRECTIVE ACTIONS:

1 CA# 189299

Corrective Action: Comply with Rule 406.c.
A CA Date of 11/16/2023 is being provided, as this is the "Start Date" for construction of the Location, per Form 42 #403597299, and when Permit information was required to be posted.

Date: 11/15/2023

Response: CA COMPLETED

Date of Completion: 01/19/2024

Operator Comment: Permitting including Form 2A (403128374) and Form 4 (403485280) have been placed on location.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with ECMC rules.

2 CA# 189300

Corrective Action: Comply with Rule 605.a.
A CA Date of 11/16/2023 is being provided, as this is the "Start Date" for construction of the Location, per Form 42 #403597299, and when signage was required.

Date: 11/16/2023

Response: CA COMPLETED

Date of Completion: 01/19/2024

Operator Comment: Signage was posted at entrance to oil and gas location.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with ECMC rules.

3 CA# 189301

Corrective Action: Comply with Rule 406.d.
A CA Date of 11/16/2023 is being provided, as this is the "Start Date" for construction of the Location, per Form 42 #403597299, and when signage was required.

Date: 11/16/2023

Response: CA COMPLETED

Date of Completion: 12/29/2023

Operator Comment: Signage was posted at the intersection of lease road.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with ECMC rules.

4 CA# 189302

Corrective Action: Comply with Form 2A #403128374 permit Condition requirements, and Rule 1002.f, A CA Date of 11/16/2023 is being provided, as this is the "Start Date" for construction of the Location, per Form 42 #403597299, and when perimeter stormwater and erosion control BMPs were required.

Date: 11/16/2023

Response: CA COMPLETED

Date of Completion: 01/19/2024

Operator Comment: Stormwater BMPs have been installed around perimeter of the pad. Drainages have been protected with settlement traps. Additional slope stabilization through seeding will be completed upon favorable conditions for seeding.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with ECMC rules.

5 CA# 189303

Corrective Action: _____ Date: 11/16/2023

Comply with Form 2A #403128374 permit Condition requirements, and Rule 1002.f and Rule 1002 little b and little c. A CA Date of 11/16/2023 is being provided, as this is the "Start Date" for construction of the Locaiton, per Form 42 #403597299, and when perimeter stormwater and erosion control BMPs were required.

Response: CA COMPLETED

Date of Completion: 01/30/2024

Operator Comment: Perimeter stormwater controls around topsoil pile have been installed. Signage on topsoil piles has been installed. Topsoil was salvaged to a depth of 6".

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with ECMC rules.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Schuyler Hamilton

Signed: _____

Title: Env. Compliance Analyst

Date: 2/1/2024 3:49:23 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

403664415	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files