

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
403678760

Date Received:
02/06/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 44390

Name of Operator: JAVERNICK OIL

Address: 3040 E MAIN

City: CANON CITY State: CO Zip: 81212

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Javernick, James

719-275-3040/719-671-3787

javernick1@gmail.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 695109054

Inspection Date: 01/24/2024

FIR Submit Date: 01/24/2024

FIR Status: _____

Inspected Operator Information:

Company Name: JAVERNICK OIL

Company Number: 44390

Address: 3040 E MAIN

City: CANON CITY State: CO Zip: 81212

LOCATION - Location ID: 322259

Location Name: HASSLER-620S69W Number: 28SESW County: FREMONT

Qtrqtr: SESW Sec: 28 Twp: 20S Range: 69W Meridian: 6

Latitude: 38.273170 Longitude: -105.115610

FACILITY - API Number: 05-043-00 Facility ID: 210079

Facility Name: HASSLER Number: 27

Qtrqtr: SESW Sec: 28 Twp: 20S Range: 69W Meridian: 6

Latitude: 38.273170 Longitude: -105.115610

CORRECTIVE ACTIONS:

1 CA# 191339

Corrective Action: Close and seal gauge hatches when not accessing tank per Rule 608.a.(9). 24 HOURS TO ADDRESS. Tanks will function as sealed and ventless with gas released only through a vapor control system or properly sized pressure relief valve. per Rule 608.a.(9). 24 HOURS TO INSTALL PRESSURE RELEIF VALVE. THIS IS THE SECOND NOTICE IMMEDIATE ACTION IS REQUIRED.

Date: _____

Response: CA COMPLETED

Date of Completion: 01/29/2024

Operator Comment: Upon inspection notification, Operator dispatched crew and closed thief hatch and installed a Jayco "Stack Vent" pressure relief valve on top of tank. See Attachment tab for photo of PRV.

COGCC Decision: _____

COGCC
Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: This FIRR advises that Operator took immediate corrective actions to close the thief hatch on top of tank and to install a Jayco "Stack Vent" pressure relief valve on riser from tank.
This FIRR also informs that Operator is seeking a variance to bradenhead testing on the Hassler 27 well, a turn of the century completion, with wellbore construction consisting of casing strings clamped or welded on without bradenhead access. Operator is concerned about hot-tapping an access into the casing and potentially damaging the casing which would in turn compromise the well integrity. At this time, there is no measurable pressure or observation of fugitive gas from the well, indicating the casing is securely isolating hydrocarbon migration.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jim Javernick

Signed: _____

Title: Owner / Manager

Date: 2/6/2024 3:46:32 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number Description

403678770	Image of top of tank (PRV)
-----------	----------------------------

Total Attach: 1 Files