

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/07/2024

Submitted Date:

02/08/2024

Document Number:

713600710

FIELD INSPECTION FORM

Loc ID Inspector Name: On-Site Inspection
 321575 COSTA, RYAN 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 61250
 Name of Operator: MULL DRILLING COMPANY INC
 Address: 1700 N WATERFRONT PKWY B#1200
 City: WICHITA State: KS Zip: 67206-

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 3 Number of Comments
 2 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
 PREVIOUS INSPECTIONS THAT HAVE NOT
 BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
OBryhim, Reesa		robryhim@mulldrilling.com	
Mull, Jennifer	(316) 264-6366	jmull@mulldrilling.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
207335	WELL	PR	03/18/2008	OW	017-06270	MULL UNIT 17	RI

General Comment:

This is a location and stormwater management inspection.
 See attached photos and additional details within this report.

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: _____

Good Housekeeping:

Type	DEBRIS		
Comment:	There is weed debris around the equipment that needs to be removed.		
Corrective Action:	Comply with Rule 606.	Date:	02/15/2024

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Material Handling And Spill Prevention	Fail	

Comment: There is oily fluids in the secondary conatinment of the barrels stored on location. Some fluids have spilled over onto the ground which need to be cleaned up. Secondary containment needs to be kept drained to prevent overflow and wildlife entry.

Corrective Action: Implement or modify BMPs for improved material handling and spill prevention. Immediately clean up area. Comply with 1002.f.(2)B

Date: 02/10/2024

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713600711	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6422748