

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/30/2024

Submitted Date:

02/06/2024

Document Number:

710500162

FIELD INSPECTION FORM

Loc ID 321180 Inspector Name: Sanchez, Chris On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10330
Name of Operator: INVESTMENT EQUIPMENT LLC
Address: 558 CASTLE PINES PKWY UNIT B-4
City: CASTLE PINES State: CO Zip: 80108

Findings:

- 5 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Freese, Steve		steve.freese@state.co.us	Land Board
Costa, Ryan		ryan.costa@state.co.us	
Bongers, Brent		bbongers@impetroresources.com	
Highberger, Kathryn		kathrynhighberger@gmail.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
276262	WELL	PA	07/17/2017	OW	009-06628	STATE OF COLORADO 3-16	EI
321180	LOCATION	CL			-	STATE OF COLORADO-635S46W 16NENE	EI

General Comment:

This is an Environmental Inspection for the State of Colorado 3-16 API# 05-009-06628 Plugged and Abandon well location located in Baca County Colorado.

Inspected Facilities

Facility ID: 276262 Type: WELL API Number: 009-06628 Status: PA Insp. Status: EI

Facility ID: 321180 Type: LOCATION API Number: - Status: CL Insp. Status: EI

Environmental

Spills/Releases:

Type of Spill: OTHER E&P WASTE Estimated Spill Volume: _____

Comment: The north side of the location appears to have impacted soils with signs of erosion. See attached Photo Log

Corrective Action: The operator shall file a Form 19 and investigate the potential historical release in accordance with Rule 912.b.(1)E

Date: 02/07/2024

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____ Comment: _____

COGCC Comments

Comment	User	Date
The north side of the location appears to have impacted soils with signs of erosion. The operator shall file a Form 19 and investigate the potential historical release in accordance with Rule 912.b.(1)E	sanchezcc	02/06/2024
All previously assigned CAs assigned to the location still apply	sanchezcc	02/06/2024

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403678880	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6420781
710500165	Location Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6420771