

FORM

6

Rev
11/20

State of Colorado

Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109

DE

ET

OE

ES

Document Number:

403587884

Date Received:

11/07/2023

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set. A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: 47120

Contact Name: CANDICE BARBER

Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP

Phone: (307) 233-4513

Address: P O BOX 173779

Fax:

City: DENVER State: CO Zip: 80217-

Email: CANDICE_BARBER@OXY.COM

For "Intent" 24 hour notice required,

Name:

Tel:

COGCC contact:

Email:

Type of Well Abandonment Report:

☐ Notice of Intent to Abandon

☒ Subsequent Report of Abandonment

API Number 05-123-14735-00

Well Name: BEEBE DRAW UPRR

Well Number: 32-5 (9)

Location: QtrQtr: SWNE Section: 5 Township: 3N Range: 65W Meridian: 6

County: WELD

Federal, Indian or State Lease Number:

Field Name: WATTENBERG

Field Number: 90750

Only Complete the Following Background Information for Intent to Abandon

Latitude: 40.256365 Longitude: -104.685649

GPS Data: GPS Quality Value: 1.2 Type of GPS Quality Value: PDOP Date of Measurement: 10/26/2023

Reason for Abandonment: ☐ Dry ☐ Production Sub-economic ☐ Mechanical Problems

☐ Other

Casing to be pulled: ☐ Yes ☐ No Estimated Depth:

Fish in Hole: ☐ Yes ☐ No If yes, explain details below

Wellbore has Uncemented Casing leaks: ☐ Yes ☐ No If yes, explain details below

Details:

Current and Previously Abandoned Zones

Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth
CODELL	7270	7280	08/02/2002	BRIDGE PLUG	4336
NIOBRARA	6985	7065	08/02/2002	BRIDGE PLUG	4336

Total: 2 zone(s)

Casing History

Date Run: 2/26/2024 Doc [#403587884] Well Name: BEEBE DRAW UPRR 32-5 (9)

Page 1 of 3

Casing Type	Size of Hole	Size of Casing	Grade	Wt/Ft	Csg/Liner Top	Setting Depth	Sacks Cmt	Cmt Btm	Cmt Top	Status
SURF	12+1/4	8+5/8	J-55	24	0	617	315	617	0	VISU
1ST	7+7/8	4+1/2	I-80	11.6	4020	7385	225	7385	6385	CBL
	7+7/8	4+1/2		Stage Tool	0	4740	150	4740	4290	CBL

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth 230 with 100 sacks cmt on top. CIBP #2: Depth _____ with _____ sacks cmt on top.
CIBP #3: Depth _____ with _____ sacks cmt on top. CIBP #4: Depth _____ with _____ sacks cmt on top.
CIBP #5: Depth _____ with _____ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set 290 sks cmt from 4005 ft. to 3460 ft. Plug Type: OPEN HOLE Plug Tagged: ☒
Set 285 sks cmt from 2500 ft. to 2011 ft. Plug Type: OPEN HOLE Plug Tagged: ☒
Set 285 sks cmt from 1700 ft. to 1138 ft. Plug Type: OPEN HOLE Plug Tagged: ☒
Set 165 sks cmt from 770 ft. to 724 ft. Plug Type: OPEN HOLE Plug Tagged: ☒
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

(Cast Iron Cement Retainer Depth)

Set 200 sacks half in. half out surface casing from 724 ft. to 235 ft. Plug Tagged: ☒

Set _____ sacks at surface

Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: ☐ Yes ☒ No

Set _____ sacks in rat hole Set _____ sacks in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing Recovered: _____ ft. of _____ inch casing Number of Days from Setting Surface Plug
Surface Plug Setting Date: 09/14/2023 Cut and Cap Date: 10/17/2023 to Capping or Sealing the Well: 33

*Wireline Contractor: NEXTIER

*Cementing Contractor: NEXTIER

Type of Cement and Additives Used: _____

Flowline/Pipeline has been abandoned per Rule 1105 ☒ Yes ☐ No

Technical Detail/Comments:

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: CANDICE BARBER

Title: REGULATORY ANALYST Date: 11/7/2023 Email: DJREGULATORY@OXY.COM

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: Jacobson, Eric Date: 2/26/2024

CONDITIONS OF APPROVAL, IF ANY:

COA Type	Description
0 COA	

Attachment List

Att Doc Num	Name
403587884	FORM 6 SUBSEQUENT SUBMITTED
403588106	WELLBORE DIAGRAM
403588107	WIRELINE JOB SUMMARY
403588108	CEMENT JOB SUMMARY
403588109	OTHER
403588110	OPERATIONS SUMMARY

Total Attach: 6 Files

General Comments

User Group	Comment	Comment Date
Permit	Operator submitted as-drilled well location per COA. Production reporting OK. Reviewed attachments. Pass.	02/23/2024

Total: 1 comment(s)