

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/16/2024

Submitted Date:

02/20/2024

Document Number:

713600757**FIELD INSPECTION FORM**Loc ID 309066 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10705Name of Operator: EVERGREEN NATURAL RESOURCES LLCAddress: 1875 LAWRENCE ST STE 1150City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**2 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Inspections, Evergreen		cogcc.evergreen@enrllc.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
309066	LOCATION	AC			-	LAUREN-631S66W 35SENE	RI

General Comment:

This is a location and stormwater management inspection of the LAUREN #42-35 wellsite.
See attached photos and additional details within this report.

Location					
Overall Good: <input type="checkbox"/>					
Signs/Marker:					
Type	WELLHEAD				
Comment:					
Corrective Action:				Date:	
Emergency Contact Number:					
Comment:					
Corrective Action:				Date:	
Overall Good: <input type="checkbox"/>					
Spills:					
Type	Area	Volume			
In Containment: No					
Comment:					
<input type="checkbox"/> Multiple Spills and Releases?					
Venting:					
Yes/No					
Comment:					
Corrective Action:				Date:	
Flaring:					
Type					
Comment:					
Corrective Action:				Date:	

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: There are areas of the access road that are not stabilized and there is vehicle rutting occurring. Areas of the road need to be stabilized with BMP's to prevent vehicle rutting.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 02/22/2024

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403692750	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6435591
713600758	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6435587