

State of Colorado Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
403694267

Date Received:
03/01/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:
3 of 3 CAs from the FIR responded to on this Form
3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635
Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>.TEP</u>		<u>COGCCInspectionReports@terraep.com</u>
<u>Toews, Wesley</u>		<u>wtoews@blm.gov</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 708902778
Inspection Date: 01/10/2024 FIR Submit Date: 01/14/2024 FIR Status: _____

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC Company Number: 96850
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 335063

Location Name: FEDERAL-66S94W Number: 17NWSE County: _____
Qtrqtr: NWSE Sec: 17 Twp: 6S Range: 94W Meridian: 6
Latitude: 39.522654 Longitude: -107.909522

FACILITY - API Number: 05-045-00 Facility ID: 335063

Facility Name: FEDERAL-66S94W Number: 17NWSE
Qtrqtr: NWSE Sec: 17 Twp: 6S Range: 94W Meridian: 6
Latitude: 39.522654 Longitude: -107.909522

CORRECTIVE ACTIONS:

1 CA# 190057

Corrective Action: Operators will ensure that signs are well maintained and legible, and will replace damaged or vandalized signs within 30 days of discovery that the sign is no longer legible or is damaged. Date: 02/13/2024

Response: CA COMPLETED Date of Completion: 02/06/2024

Operator Comment: Weathered tank battery sign has been replaced. Corrective Action complete.

COGCC Decision: _____

COGCC Representative: _____

2 CA# 190058

Corrective Action: All guy line anchors left buried for future use will be identified by a marker of bright color not less than 4 feet in height and not greater than 1 foot east of the guy line anchor.

Date: 01/28/2024

Response: CA COMPLETED

Date of Completion: 01/16/2024

Operator Comment: The unmarked deadman was marked. Corrective Action complete.

COGCC Decision: _____

COGCC Representative: _____

3 CA# 190059

Corrective Action: Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. BMPs shall be maintained until the facility is abandoned and final reclamation is achieved.

Date: 01/29/2024

Response: CA COMPLETED

Date of Completion: 01/19/2024

Operator Comment: Stormwater control measures have been maintained. Corrective Action complete.

COGCC Decision: _____

COGCC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: CA #190057: Weathered tank battery sign has been replaced. Corrective Action complete.
CA #190058: The unmarked deadman was marked. Corrective Action complete.
CA #190059: Stormwater control measures have been maintained. Corrective Action complete.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jordan Veith

Signed: _____

Title: TEP Representative

Date: 3/1/2024 12:15:49 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number	Description

Total Attach: 0 Files