

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/26/2024

Submitted Date:

02/26/2024

Document Number:

702502421

FIELD INSPECTION FORM

Loc ID 314975 Inspector Name: Burchett, Kirby On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 11 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Wilson, Justin	(970) 878-3825	jrwilson@blm.gov	
, TEP	(970) 285-9377	COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
230003	WELL	PR	07/01/2021	GW	103-07662	GOVT-EQUITY 298-26-2	PR

General Comment:

[ECMC Inspection Report Summary](#)

On Monday, 02/26/2024, Inspector Kirby Burchett, conducted a routine field inspection at TEP Rocky Mountain LLC on the Gov't-Equity 298-26-2 well, Location #314975, in Moffat County, Colorado.

This location is within or in close proximity to Parks and Wildlife (CPW) District, Black Bear and High Priority Habitat area with NSO Habitat regulations.

Any Corrective Actions from previous Inspections are still applicable.

While there during normal production operations the following compliance issues were observed:

1. Production tank missing required information.
- Refer to Inspection Photos for observed compliance issues.

A follow up on this site inspection will be conducted to ensure all compliance issues have been corrected to comply with ECMC rules.

Location

Overall Good:

Signs/Marker:

Type	OTHER		
Comment:	Separator units include attached storage tanks. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Tank missing reuired information		
Corrective Action:	All Tanks and Containers will be labeled pursuant to Rule 605. h. (1). All Tanks with a capacity of 10 Barrels or greater will be labeled or posted with the following information: Name of Operator; Operator's emergency contact telephone number; Tank capacity; Tank contents; and NFPA label or equivalent globally harmonized label.		Date: 03/08/2024
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 970-285-9377 or 911

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:	Cattle panels		
Corrective Action:		Date:	

Equipment:

Type:		#		corrective date
Bird Protectors		# 1		
Comment:				
Corrective Action:			Date:	
Bradenhead		# 1		
Comment:				
Corrective Action:			Date:	
Horizontal Heated Separator		# 1		
Comment:				

Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Outside meter. Calibration located in box.		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Wellhead		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	<100 BBLS	STEEL AST		
Comment:	Buried tank is located 4 feet from separator and 30 feet from wellhead. Pre-1986 construction so minimum setbacks of 75 feet is waived unless equipment is changed out then 1986 rules will apply.				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			
Comment:	Unlined			
Corrective Action:				Date:

Venting:

Yes/No	NO
Comment:	
Corrective Action:	Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 230003 Type: WELL API Number: 103-07662 Status: PR Insp. Status: PR

Producing Well

Comment: [December 2023 Production Report](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches				
Berms						

Comment: Operator is responsible for maintaining Best Management Practices (BMPs) to control vehicle tracking and potential sediment discharges from operational roads, well pads, and other unpaved surfaces.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403699024	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6443486
702502422	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6443481